

LIEBHERR

CONSTRUCTION EQUIPMENT



LIEBHERR LH30M 150670-1253 - Front Right Wheel Hub

Sample No: LH0271943

Oil Type: NOT GIVEN



Gestion Transfor - Transport La Dore
 5750 Rue des Peupliers
 La Dore, QC
 CA G8J 1G4
 Contact: Eric Fortin
 efortin.transfor@hotmail.com
 T: (418)258-1182
 F: (418)256-3973



SAMPLE INFORMATION

Sample Number	LH0271943	LH0271931	---	---
Sample Date	13 Oct 2023	01 Sep 2023	---	---
Machine Hours	825	458	---	---
Oil Hours	0	0	---	---
Oil Changed	N/A	N/A	---	---
Sample Status	NORMAL	NORMAL	---	---



OIL CONDITION

Visc @ 40°C	cSt	64.1	64.3	---	---
-------------	-----	------	------	-----	-----



CONTAMINATION

Silicon	ppm	5	6	---	---
Sodium	ppm	21	21	---	---
Potassium	ppm	1	1	---	---



WEAR METALS

Iron	ppm	73	60	---	---
Copper	ppm	29	27	---	---
Lead	ppm	1	<1	---	---
Tin	ppm	0	0	---	---
Aluminum	ppm	1	1	---	---
Chromium	ppm	<1	<1	---	---
Molybdenum	ppm	0	<1	---	---
Nickel	ppm	<1	<1	---	---
Titanium	ppm	0	<1	---	---
Silver	ppm	<1	0	---	---
Manganese	ppm	<1	2	---	---
Vanadium	ppm	0	0	---	---



ADDITIVES

Calcium	ppm	3434	3376	---	---
Magnesium	ppm	10	10	---	---
Zinc	ppm	1384	1372	---	---
Phosphorus	ppm	1138	1183	---	---
Barium	ppm	2	2	---	---
Boron	ppm	96	94	---	---

Diagnosis

Échantillonner de nouveau l'équipement au prochain intervalle de vidange afin d'en surveiller la condition. Veuillez préciser la marque, le type et la viscosité de l'huile lors de votre prochain échantillon. Les taux d'usure de tous les composants sont normaux. Il n'y a aucun indice de contamination dans l'huile. L'état de l'huile est acceptable pour la durée de service.

Depot: TRALAD
Unique No: 5659782
Signed: Kevin Marson
Report Date: 20 Oct 2023



GRAPHS

