

LIEBHERR

CONSTRUCTION EQUIPMENT



LIEBHERR LH30M 150670-1253 - Front Left Wheel Hub

Sample No: LH0271942

Oil Type: NOT GIVEN



Gestion Transfor - Transport La Dore
 5750 Rue des Peupliers
 La Dore, QC
 CA G8J 1G4
 Contact: Eric Fortin
 efortin.transfor@hotmail.com
 T: (418)258-1182
 F: (418)256-3973



SAMPLE INFORMATION

Sample Number	LH0271942	LH0271930	---	---
Sample Date	13 Oct 2023	01 Sep 2023	---	---
Machine Hours	825	458	---	---
Oil Hours	0	0	---	---
Oil Changed	N/A	N/A	---	---
Sample Status	NORMAL	NORMAL	---	---



OIL CONDITION

Visc @ 40°C	cSt	64.2	65.8	---	---
-------------	-----	------	------	-----	-----



CONTAMINATION

Silicon	ppm	5	5	---	---
Sodium	ppm	20	21	---	---
Potassium	ppm	1	1	---	---



WEAR METALS

Iron	ppm	65	56	---	---
Copper	ppm	26	23	---	---
Lead	ppm	1	<1	---	---
Tin	ppm	0	0	---	---
Aluminum	ppm	1	1	---	---
Chromium	ppm	<1	<1	---	---
Molybdenum	ppm	0	0	---	---
Nickel	ppm	<1	<1	---	---
Titanium	ppm	0	0	---	---
Silver	ppm	<1	0	---	---
Manganese	ppm	<1	1	---	---
Vanadium	ppm	0	0	---	---



ADDITIVES

Calcium	ppm	3468	3425	---	---
Magnesium	ppm	10	10	---	---
Zinc	ppm	1408	1397	---	---
Phosphorus	ppm	1165	1202	---	---
Barium	ppm	2	2	---	---
Boron	ppm	99	96	---	---

Diagnosis

Échantillonner de nouveau l'équipement au prochain intervalle de vidange afin d'en surveiller la condition. Veuillez préciser la marque, le type et la viscosité de l'huile lors de votre prochain échantillon. Les taux d'usure de tous les composants sont normaux. Il n'y a aucun indice de contamination dans l'huile. L'état de l'huile est acceptable pour la durée de service.

Depot: TRALAD
Unique No: 5659786
Signed: Wes Davis
Report Date: 20 Oct 2023



GRAPHS

