LIEBHERR

CONSTRUCTION EQUIPMENT

LIEBHERR A904 056759-005 - Front Right Wheel Hub

Sample No: LH

Oil Type: NOT GIVEN

_					
SAMPLEINFORMATION					
Sample Number		LH			
Sample Date		18 Oct 2023			
Machine Hours		14788			
Oil Hours		0			
		N/A			
Oil Changed					
Sample Status NORMAL					
OIL C	ONDITION				
Visc @ 40°C	cSt	97.4			
		0 3111			
CONTAMINATION					
CONT	AMINATI				
Silicon	ppm	2			
Sodium	ppm	2			
Potassium	ppm	0			
WEAR METALS					
Iron	ppm	56			
Copper	ppm	7			
Lead	ppm	4			
Tin	ppm	0			
Aluminum	ppm	0 <1			
Chromium	ppm	0			
Molybdenum	ppm	0			
Nickel	ppm	0			
Titanium	ppm	0 0			
Silver	ppm	<1			
Manganese	ppm	0			
Vanadium	ppm	0			
THE STATE OF THE S					
ADDITIVES					
Calcium	ppm	351			
Magnesium	ppm	2			
Zinc	ppm	168			
Phosphorus	ppm	1307			
Barium	ppm	2			
Boron	ppm	204			
	1.7				



LIEBHERR CANADA LTEE 444 AVENUE DE LA FRICHE DOLBEAU-MISTASSINI, QC CA G8L 3M7 Contact: Luc Trottier

luc.trottier@liebherr.com

T:

F: (418)276-9844

Diagnosis

Resample at the next service interval to monitor. Please specify the brand, type, and viscosity of the oil on your next sample.All component wear rates are normal. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.

Depot: LBADOL
Unique No: 5668901
Signed: Kevin Marson
Report Date: 25 Oct 2023

LIEBHERR

CONSTRUCTION EQUIPMENT





GRAPHS

