LIEBHERR

CONSTRUCTION EQUIPMENT

LIEBHERR LH30M 139969-1253 - Rear Right Wheel Hub

Sample No: LH

Oil Type: NOT GIVEN

SAMPLE INFORMATION						
Sample Number	LH					
Sample Date	19 Oct 2023					
Machine Hours	480					
Oil Hours	0					
Oil Changed	N/A					
Sample Status	NORMAL					

	- 1011010				
0	OIL CO	NDITION			
Visc @	40°C	cSt	65.8	 	

CONT	AMINATIO	ON		
Silicon	ppm	8	 	
Sodium	ppm	18	 	
Potassium	ppm	0 <1	 	

WEA	R METALS			
Iron	ppm	6	 	
Copper	ppm	5	 	
Lead	ppm	0	 	
Tin	ppm	0	 	
Aluminum	ppm	○ <1	 	
Chromium	ppm	0	 	
Molybdenum	ppm	0	 	
Nickel	ppm	0	 	
Titanium	ppm	0	 	
Silver	ppm	<1	 	
Manganese	ppm	1	 	
Vanadium	ppm	0	 	

ADD	DITIVES			
Calcium	ppm	3605	 	
Magnesium	ppm	10	 	
Zinc	ppm	1390	 	
Phosphorus	ppm	1161	 	
Barium	ppm	<1	 	
Boron	ppm	105	 	



METAUX 139 INC. 86 RTE MARIE-VICTORIN PIERREVILLE, QC CA J0G 1J0 Contact: Service Manager

T: F:

Diagnosis

Resample at the next service interval to monitor. Please specify the brand, type, and viscosity of the oil on your next sample.All component wear rates are normal. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.

Depot:MET126WICUnique No:5668923Signed:Kevin MarsonReport Date:25 Oct 2023

LIEBHERR







GRAPHS

