

LIEBHERR

CONSTRUCTION EQUIPMENT



LIEBHERR LH30M 139969-1253 - Front Right Wheel Hub

Sample No: LH
 Oil Type: NOT GIVEN



METAUX 139 INC.
 86 RTE MARIE-VICTORIN
 PIERREVILLE, QC
 CA J0G 1J0
 Contact: Service Manager



SAMPLE INFORMATION

Sample Number	LH	---	---	---
Sample Date	19 Oct 2023	---	---	---
Machine Hours	480	---	---	---
Oil Hours	0	---	---	---
Oil Changed	N/A	---	---	---
Sample Status	NORMAL	---	---	---



OIL CONDITION

Visc @ 40°C	cSt	67.9	---	---	---
-------------	-----	------	-----	-----	-----

T:
 F:



CONTAMINATION

Silicon	ppm	5	---	---	---
Sodium	ppm	21	---	---	---
Potassium	ppm	<1	---	---	---

Diagnosis

Resample at the next service interval to monitor. Please specify the brand, type, and viscosity of the oil on your next sample. All component wear rates are normal. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.



WEAR METALS

Iron	ppm	16	---	---	---
Copper	ppm	12	---	---	---
Lead	ppm	<1	---	---	---
Tin	ppm	0	---	---	---
Aluminum	ppm	<1	---	---	---
Chromium	ppm	<1	---	---	---
Molybdenum	ppm	0	---	---	---
Nickel	ppm	0	---	---	---
Titanium	ppm	0	---	---	---
Silver	ppm	<1	---	---	---
Manganese	ppm	<1	---	---	---
Vanadium	ppm	0	---	---	---



ADDITIVES

Calcium	ppm	3511	---	---	---
Magnesium	ppm	9	---	---	---
Zinc	ppm	1367	---	---	---
Phosphorus	ppm	1134	---	---	---
Barium	ppm	<1	---	---	---
Boron	ppm	103	---	---	---

Depot: MET126WIC
 Unique No: 5668925
 Signed: Kevin Marson
 Report Date: 25 Oct 2023



GRAPHS

