LIEBHERR

CONSTRUCTION EQUIPMENT

LIEBHERR LB24 115316 - Splitter Box

Sample No: LH0274349

Molybdenum

Nickel

Silver

Titanium

Manganese

Vanadium

Calcium

Zinc

Barium

Boron

Magnesium

Phosphorus

ppm

ADDITIVES

Oil Type: PETRO CANADA TRAXON 75W90 SYNTHETIC

0

0<1

0

0

<1

0

10


2

18

<1</p>

263

1373



0

 \bigcirc 0

09

 \bigcirc 0

13

 \bigcirc <1

293

0 1276



LIEBHERR CANADA LTD.

10374 267 ST. ACHESON, AB CA T7X 6A2

Contact: Rodney Budzak rodney.budzak@liebherr.com

T: (780)962-6799 F: (780)962-6799

Diagnosis

Resample at the next service interval to monitor. All component wear rates are normal. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.

Depot: LIESPR
Unique No: 5670782
Signed: Wes Davis
Report Date: 02 Nov 2023

LIEBHERR

CONSTRUCTION EQUIPMENT





GRAPHS

