

[(343449)] 126043-1215 - Splitter Box

Sample No: LH0278373

Oil Type: SAE 75W90

SAMPLE INFORMATION

Sample Nur	nber	LH0278373	LH0230438	
Sample Dat	e	23 Nov 2023	12 Aug 2022	
Machine Ho	urs	1248	497	
Oil Hours		0	0	
Oil Changeo	ł	Changed	Changed	
Sample Stat	tus	NORMAL	NORMAL	

OIL CONDITION Visc @ 40°C cSt 0 101 193 --

Water	%	NEG	NEG			
Silicon	ppm	0 2	0 2			
Sodium	ppm	02	0 4			
Potassium	ppm	○ <1	0 2			

Ä				
WEA	R METAI	LS		
		0.45	0.40	
Iron	ppm	0 15	0 16	
Copper	ppm	<mark></mark>	2	
Lead	ppm	○ <1	○ <1	
Tin	ppm	0 (0	
Aluminum	ppm	○ <1	○ <1	
Chromium	ppm	0	0	
Molybdenum	ppm	0 2	0	
Nickel	ppm	0 🔘	0	
Titanium	ppm	0	0	
Silver	ppm	<1	0	
Manganese	ppm	0	03	
Vanadium	ppm	0	0	

	TIVES			
Calcium	ppm	70	0 16	
Magnesium	ppm	40	0 6	
Zinc	ppm	69	0 14	
Phosphorus	ppm	0 1237	0 1612	
Barium	ppm	○ <1	◯ <1	
Boron	ppm	243	0 2	





American Iron and Metal 524 PORTSWAY AVE EDWARDSVILLE, NS CA B2A 0C2 Contact: Service Manager

T: F:

Diagnosis

Resample at the next service interval to monitor.All component wear rates are normal. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.

Depot:AIMSYDUnique No:5683948Signed:Kevin MathingReport Date:24 Nov 2


5683948 Kevin Marson 24 Nov 2023





GRAPHS

 \odot



Report Id: AIMSYD [WCAMIS] 02598868 (Generated: 11/24/2023 16:29:20) Rev: 1