

## LIEBHERR LH50M 150728-1216 - Front Left Wheel Hub

Sample No: LH0242073

Oil Type: PETRO CANADA TRAXON SYNTHETIC 75W90

SAMPLE INFORMATION						
Sample Number	LH0242073					
Sample Date	21 Nov 2023					
Machine Hours	500					
Oil Hours	500					
Oil Changed	Changed					
Sample Status	NORMAL					
OIL CONDITION						

Sample Status		NORMAL					
OIL CONDITION							
Visc @ 40°C	cSt	<b>151</b>					

CONTAMINATION								
Water	%	NEG						
Silicon	ppm	<b>8</b>						
Sodium	ppm	<b>5</b>						
Potassium	ppm	<b>0</b> <1						

(O)				
₩ WEA	AR META	LS		
Iron	ppm	<b>49</b>	 	
Copper	ppm	<b>24</b>	 	
Lead	ppm	<b>()</b> <1	 	
Tin	ppm	<b>0</b>	 	
Aluminum	ppm	<b>()</b> <1	 	
Chromium	ppm	<b>0</b>	 	
Molybdenum	ppm	<b>0</b>	 	
Nickel	ppm	<b>○</b> <1	 	
Titanium	ppm	0	 	
Silver	ppm	<1	 	
Manganese	ppm	<b>2</b>	 	
Vanadium	ppm	0	 	

ADDITIVES						
Calcium	ppm	<b>8</b>				
Magnesium	ppm	<b>()</b> <1				
Zinc	ppm	<b>14</b>				
Phosphorus	ppm	<b>1111</b>				
Barium	ppm	<b>()</b> <1				
Boron	ppm	<b>2</b>				



**ABC RECYCLING** 750C JACKSON RD NANAIMO, BC CA V9X 1J2 Contact: Jordie Richmond

jordie.richmond@abcrecycling.com

T: (250)202-8235

F:

#### Diagnosis

Resample at the next service interval to monitor.All component wear rates are normal. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.

Depot: **ABCNAN Unique No:** 5684399 Signed: Wes Davis Report Date: 28 Nov 2023

# LIEBHERR

CONSTRUCTION EQUIPMENT





### **GRAPHS**

