CONSTRUCTION EQUIPMENT

059596-194 - Rear Right Wheel Hub

<1

0 (

06

○ <1

0 15

○ <1

0 297

0 1243

0

ppm

ppm

ppm

ppm

ppm

ppm

ppm

ppm

ppm

ADDITIVES

LH0274780 Sample No:

Silver

Manganese

Vanadium

٥

Calcium

Zinc

Barium

Boron

Magnesium

Phosphorus

Oil Type:	PETRO CA	NADA TRAXON	75W90 SYNTHE	ETIC	
ā.					
SAM	PLE INFOR	MATION			
Sample Number		LH0274780	LH0256515	LH0202808	LH0202913
Sample Date		23 Nov 2023	21 Mar 2023	15 Nov 2022	04 Nov 2021
Machine Hours		19244	18037	17530	16550
Oil Hours		0	0	0	0
Oil Changed		Changed	Changed	Changed	Changed
Sample Status		NORMAL	NORMAL	NORMAL	NORMAL
OIL C	ONDITION				
Visc @ 40°C	cSt	0 106	0 101	0 102	0 102
- 1					
CONT	AMINATI	ON			
Water	%	NEG	NEG	NEG	NEG
Silicon	ppm	03	02	2	2

Sodium	ppm	○ <1	◯ <1	◯ <1	◯ <1	
Potassium	ppm	0 🔘	○ <1	◯ <1	○ <1	
~						
	AR META	LS				
Iron	ppm	0 2	5	0 4	3	
Copper	ppm	0 14	◯ 39	36	26	
Lead	ppm	○ <1	0 1	◯ <1	○ <1	
Tin	ppm	0 🔘	0	0	○ <1	
Aluminum	ppm	0 🔘	0	◯ <1	0	
Chromium	ppm	0 (0	0	0	
Molybdenum	ppm	0 (0	0	0	
Nickel	ppm	○ <1	0	0	0	
Titanium	ppm	0	0	0	0	

○ <1

9

○ <1

0 23

 $\bigcirc 0$

0 1349

◯ 314

<1

9

○ <1

0 22

0

0 317

0 1315



○ <1

0 10

 \bigcirc <1

0 16

 $\bigcirc 0$

0 1383

0 337

2555 Sheffield Road CA K1B 3V6 Contact: Dan Dupelle ddupelle@aim-rg.com T: (613)228-9380 F: (613)745-0692

Diagnosis

Resample at the next service interval to monitor.All component wear rates are normal. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.

	538	
MARKE		

Depot:	BAKOTT
Unique No:	5684834
Signed:	Wes Davis
Report Date:	30 Nov 2023





GRAPHS

0

