CONSTRUCTION EQUIPMENT

LIEBHERR R945 055435-1866 - Splitter Box

PETRO CANADA TRAXON 75W90 SYNTHETIC

Sample No: LH0252139

Oil Type:

SAMPLE INFORMATION

Sample Number	LH0252139	LH0252132	LH0256975	
Sample Date	27 Nov 2023	31 Jul 2023	27 Mar 2023	
Machine Hours	2001	1467	1015	
Oil Hours	0	0	0	
Oil Changed	Changed	Changed	Changed	
Sample Status	NORMAL	NORMAL	NORMAL	
OIL CONDITION				
Visc @ 40°C cSt	0 149	120	0 185	

	NTAMINA	TION			
Water	%	NEG	NEG	NEG	
Silicon	ppm	04	0 1	2	
Sodium	ppm	0 2	2	2	
Potassium	ppm	○ <1	01	02	

Ä					
WEA	R META	LS			
Iron	ppm	24	0 19	◯ 30	
Copper	ppm	<mark>()</mark> <1	◯ <1	◯ <1	
Lead	ppm	○ <1	0	◯ <1	
Tin	ppm	0 (0	0	
Aluminum	ppm	01	◯ <1	◯ <1	
Chromium	ppm	0 (0	◯ <1	
Molybdenum	ppm	0 (0	0	
Nickel	ppm	<mark></mark> <1	○ <1	0	
Titanium	ppm	0	0	<1	
Silver	ppm	<1	0	0	
Manganese	ppm	0 (◯ <1	◯ <1	
Vanadium	ppm	0	0	0	

Q

Calcium	ppm	9	8	0 11	
Magnesium	ppm	○ <1	01	02	
Zinc	ppm	0 12	0 17	0 15	
Phosphorus	ppm	1935	0 1454	0 1665	
Barium	ppm	○ <1	0	0	
Boron	ppm	75	0 197	0 15	



CLOUTHIER VENTURES LTD.

59 MATTHEWS STREET, R.R. # 5 PEMBROKE, ON CA K8A 0A6 Contact: Travis Bennett tbennett@clouthierconst.com T: (613)735-6531 F: (613)735-2769

Diagnosis

Confirm the source of the lubricant being utilized for top-up/fill. Resample at the next service interval to monitor.All component wear rates are normal. There is no indication of any contamination in the oil. Additive levels indicate the addition of a different brand, or type of oil. The condition of the oil is acceptable for the time in service.

Depot:	CLC
Unique No:	5684
Signed:	Wes
Report Date:	30 N

OPEM 84978 es Davis 1 Nov 2023





GRAPHS

 $\overline{\mathbf{O}}$

