

LIEBHERR

CONSTRUCTION EQUIPMENT



LIEBHERR LH80M 149850-1218 - Rear Differential

Sample No: LH0091167

Oil Type: PETRO CANADA TRAXON SYNTHETIC 75W90



ARCELORMITTAL LONG PRODUITS CANADA
3185 ROUTE MARIE-VICTORIN
CONTRECOEUR, QC
CA J0L 1C0
Contact: Danny Drouin
danny.drouin@arcelormittal.com
T:
F:



SAMPLE INFORMATION

Sample Number	LH0091167	---	---	---
Sample Date	29 Nov 2023	---	---	---
Machine Hours	467	---	---	---
Oil Hours	0	---	---	---
Oil Changed	Changed	---	---	---
Sample Status	NORMAL	---	---	---



OIL CONDITION

Visc @ 40°C	cSt	● 147	---	---	---
-------------	-----	-------	-----	-----	-----



CONTAMINATION

Water	%	NEG	---	---	---
Silicon	ppm	● 9	---	---	---
Sodium	ppm	● 3	---	---	---
Potassium	ppm	● <1	---	---	---



WEAR METALS

Iron	ppm	● 34	---	---	---
Copper	ppm	● 9	---	---	---
Lead	ppm	● <1	---	---	---
Tin	ppm	● 0	---	---	---
Aluminum	ppm	● <1	---	---	---
Chromium	ppm	● 0	---	---	---
Molybdenum	ppm	● 1	---	---	---
Nickel	ppm	● <1	---	---	---
Titanium	ppm	0	---	---	---
Silver	ppm	<1	---	---	---
Manganese	ppm	● <1	---	---	---
Vanadium	ppm	0	---	---	---



ADDITIVES

Calcium	ppm	● 215	---	---	---
Magnesium	ppm	● 1	---	---	---
Zinc	ppm	● 45	---	---	---
Phosphorus	ppm	● 1492	---	---	---
Barium	ppm	● 1	---	---	---
Boron	ppm	● 9	---	---	---

Diagnosis

Échantillonner de nouveau l'équipement au prochain intervalle de vidange afin d'en surveiller la condition. Les taux d'usure de tous les composants sont normaux. Il n'y a aucun indice de contamination dans l'huile. L'état de l'huile est acceptable pour la durée de service.

Depot: MITCON
Unique No: 5685713
Signed: Wes Davis
Report Date: 05 Dec 2023



GRAPHS

