LIEBHERR

CONSTRUCTION EQUIPMENT

LIEBHERR LH30M 145273-1253 - Diesel Engine

Sample No: LH

Oil Type: PETRO CANADA DURON UHP 5W30

5							
SAMPLEINFORMATION							
Sample Number		LH					
Sample Date		20 Dec 2023					
Machine Hours		500					
Oil Hours		0					
Oil Changed		Changed					
Sample Status		NORMAL					
A							

OIL (OIL CONDITION							
Visc @ 100°C	cSt	11.7						
Oxidation (PA)	%	188						
_								

CONTAMINATION						
Water	%	NEG				
Soot %	%	0 0				
Nitration (PA)	%	98				
Sulfation (PA)	%	104				
Glycol	%	NEG				
Fuel	%	<1.0				
Silicon	ppm	7				
Sodium	ppm	2				
Potassium	ppm	4				

(A)				
WEA	R META	LS		
Iron	ppm	11	 	
Copper	ppm	177	 	
Lead	ppm	8	 	
Tin	ppm	1	 	
Aluminum	ppm	4	 	
Chromium	ppm	2	 	
Molybdenum	ppm	55	 	
Nickel	ppm	 <1	 	
Titanium	ppm	0	 	
Silver	ppm	0	 	
Manganese	ppm	 <1	 	
Vanadium	ppm	0	 	

ADDITIVES							
ppm	1364						
ppm	879						
ppm	842						
ppm	667						
ppm	19						
ppm	104						
	ppm ppm ppm ppm ppm	ppm 1364 ppm 879 ppm 842 ppm 667 ppm 19	ppm 1364 ppm 879 ppm 842 ppm 667 ppm 19	ppm 1364 ppm 842 ppm 667 ppm 19			



METALEX RECYCLAGE 1646 ROUTE 169 SAINT-FELICIEN, QC CA G8K 3A2

Contact: Service Manager

T: F:

Diagnosis

Confirm the source of the lubricant being utilized for top-up/fill.

Resample at the next service interval to monitor. Metal levels are typical for a new component breaking in. There is no indication of any contamination in the oil. Additive levels indicate the addition of a different brand, or type of oil. The condition of the oil is acceptable for the time in service.

 Depot:
 MET164SAI

 Unique No:
 5698267

 Signed:
 Kevin Marson

 Report Date:
 27 Dec 2023

LIEBHERR







GRAPHS

