LIEBHERR

CONSTRUCTION EQUIPMENT



[(355228)] LIEBHERR LH60M 114198-1217 - Rear Right Wheel

Sample No: LH0225129

Oil Type: PETRO CANADA TRAXON 75W90 SYNTHETIC

Ō SAN	PLE INF	ORMATION			
Sample Number		LH0225129	LH0269772	LH0225075	LH0224840
Sample Date		07 Dec 2023	22 Sep 2023	10 Feb 2023	18 Nov 2022
Machine Hours		8004	7355	4980	4073
Oil Hours		0	0	0	0
Oil Changed		Changed	Changed	Changed	Changed
Sample Status		NORMAL	NORMAL	NORMAL	NORMAL
OIL	ONDITI	ON			
Visc @ 40°C	cSt	102	O 105	96.8	106
CON	TAMINA	ATION			

CONTAMINATION							
Water	%	NEG	NEG	NEG	NEG		
Silicon	ppm	1	O 2	O 2	O <1		
Sodium	ppm	 <1	O <1	O <1	1		
Potassium	ppm	0 <1	O <1	O <1	O <1		

WEA WEA	R META	LS			
Iron	ppm	6	O 11	1 3	0 8
Copper	ppm	5	O 14	7	O 11
Lead	ppm	() <1	O <1	O 0	O <1
Tin	ppm	0	O 0	O 0	O 0
Aluminum	ppm	 <1	O <1	O 0	O 0
Chromium	ppm	0	O 0	O 0	O 0
Molybdenum	ppm	0	0	O 0	O 0
Nickel	ppm	○ <1	0	O 0	O 0
Titanium	ppm	0	0 0	O 0	O 0
Silver	ppm	0	<1	0	0
Manganese	ppm	0	0	O <1	O <1
Vanadium	ppm	0	0	0	0

Vanadium	ppm	0	0	0	0	
ADDITIVES						
Calcium	ppm	38	8	1 0	5	
Magnesium	ppm	2	O 1	2	O 2	
Zinc	ppm	26	O 15	14	O 16	
Phosphorus	ppm	1213	O 1240	O 1294	1007	
Barium	ppm	0	O <1	O	O <1	
Boron	ppm	300	○ 316	284	O 159	



AltaSteel
9401 34 St NW
Edmonton, AB
CA T6B 2X6
Contact: Richard Bailey
richard.bailey@altasteel.com

T: F:

Diagnosis

Confirm the source of the lubricant being utilized for top-up/fill.
Resample at the next service interval to monitor. All component wear rates are normal. There is no indication of any contamination in the oil. Additive levels indicate the addition of a different brand, or type of oil. The condition of the oil is acceptable for the time in service.

Depot:ALT940EDMUnique No:5708321Signed:Kevin MarsonReport Date:09 Jan 2024

CONSTRUCTION EQUIPMENT





GRAPHS

