

LIEBHERR

CONSTRUCTION EQUIPMENT



[(355228)] LIEBHERR LH60M 114198-1217 - Rear Left Wheel H

Sample No: LH0225128

Oil Type: PETRO CANADA TRAXON 75W90 SYNTHETIC



SAMPLE INFORMATION

Sample Number	LH0225128	LH0250389	LH0225074	LH0224848
Sample Date	07 Dec 2023	22 Sep 2023	10 Feb 2023	18 Nov 2022
Machine Hours	8004	7355	4980	4073
Oil Hours	0	0	0	0
Oil Changed	Changed	Changed	Changed	Changed
Sample Status	NORMAL	NORMAL	NORMAL	NORMAL

AltaSteel
 9401 34 St NW
 Edmonton, AB
 CA T6B 2X6
 Contact: Richard Bailey
 richard.bailey@altasteel.com
 T:
 F:



OIL CONDITION

Visc @ 40°C	cSt	102	104	96.8	105



CONTAMINATION

Water	%	NEG	NEG	NEG	NEG
Silicon	ppm	1	2	2	<1
Sodium	ppm	<1	<1	<1	1
Potassium	ppm	<1	<1	<1	<1



WEAR METALS

Iron	ppm	6	12	12	8
Copper	ppm	5	14	7	12
Lead	ppm	0	<1	0	<1
Tin	ppm	0	0	0	0
Aluminum	ppm	<1	0	0	0
Chromium	ppm	0	0	0	0
Molybdenum	ppm	0	0	0	0
Nickel	ppm	<1	0	0	0
Titanium	ppm	0	0	0	0
Silver	ppm	0	<1	0	0
Manganese	ppm	0	0	<1	<1
Vanadium	ppm	0	0	0	0



ADDITIVES

Calcium	ppm	36	6	10	5
Magnesium	ppm	<1	1	2	2
Zinc	ppm	25	14	14	16
Phosphorus	ppm	1233	1263	1268	1029
Barium	ppm	0	<1	0	<1
Boron	ppm	306	315	280	164

Diagnosis

Confirm the source of the lubricant being utilized for top-up/fill. Resample at the next service interval to monitor. All component wear rates are normal. There is no indication of any contamination in the oil. Additive levels indicate the addition of a different brand, or type of oil. The condition of the oil is acceptable for the time in service.

Depot: ALT940EDM
Unique No: 5708322
Signed: Kevin Marson
Report Date: 09 Jan 2024



GRAPHS

