LIEBHERR

CONSTRUCTION EQUIPMENT

LIEBHERR LH60M 146891-1217 - Front Left Wheel Hub

Sample No: LH0281176

Oil Type: PETRO CANADA TRAXON SYNTHETIC 75W90

5					
SAMI	PLE INFO	RMATION			
Sample Number		LH0281176			
Sample Date		22 Dec 2023			
Machine Hours		519			
Oil Hours		0			
Oil Changed		Changed			
Sample Status		NORMAL			
OIL CO	ONDITION	4			
Visc @ 40°C	cSt	141			
CONTAMINATION					

CONTAMINATION					
Water	%	NEG			
Silicon	ppm	2			
Sodium	ppm	5			
Potassium	ppm	2			

WEA	R METAI	LS		
Iron	ppm	67	 	
Copper	ppm	6	 	
Lead	ppm	<1	 	
Tin	ppm	0 0	 	
Aluminum	ppm	1	 	
Chromium	ppm	○ <1	 	
Molybdenum	ppm	0	 	
Nickel	ppm	○ <1	 	
Titanium	ppm	0	 	
Silver	ppm	0	 	
Manganese	ppm	2	 	
Vanadium	ppm	0	 	

ITIVES				
ppm	14			
ppm	2			
ppm	22			
ppm	1666			
ppm	15			
ppm	119			
	ppm ppm ppm ppm ppm	ppm	ppm 14 ppm 2 ppm 22 ppm 1666 ppm 15	ppm 14 ppm 2 ppm 22 ppm 1666 ppm 15



RICHMOND STEEL RECYCLING

11760 MITCHELL ROAD RICHMOND, BC CA V6V 1V8 Contact: Aaron Kaetler

Contact: Aaron Kaetler AKaetler@richmondsteel.ca

T:

F: (604)324-8617

Diagnosis

Resample at the next service interval to monitor. All component wear rates are normal. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.

Depot:RIC117RICUnique No:5708358Signed:Kevin MarsonReport Date:08 Jan 2024

LIEBHERR







GRAPHS

