

LIEBHERR

CONSTRUCTION EQUIPMENT



LIEBHERR LH60M 146891-1217 - Front Right Wheel Hub

Sample No: LH0281174

Oil Type: PETRO CANADA TRAXON 75W90 SYNTHETIC



RICHMOND STEEL RECYCLING
 11760 MITCHELL ROAD
 RICHMOND, BC
 CA V6V 1V8
 Contact: Aaron Kaetler
 AKAetler@richmondsteel.ca
 T:
 F: (604)324-8617



SAMPLE INFORMATION

Sample Number	LH0281174	---	---	---
Sample Date	22 Dec 2023	---	---	---
Machine Hours	519	---	---	---
Oil Hours	0	---	---	---
Oil Changed	Changed	---	---	---
Sample Status	NORMAL	---	---	---



OIL CONDITION

Visc @ 40°C	cSt	● 141	---	---	---
-------------	-----	-------	-----	-----	-----



CONTAMINATION

Water	%	NEG	---	---	---
Silicon	ppm	● 2	---	---	---
Sodium	ppm	● 6	---	---	---
Potassium	ppm	● 2	---	---	---



WEAR METALS

Iron	ppm	● 62	---	---	---
Copper	ppm	● 7	---	---	---
Lead	ppm	● <1	---	---	---
Tin	ppm	● 0	---	---	---
Aluminum	ppm	● 1	---	---	---
Chromium	ppm	● <1	---	---	---
Molybdenum	ppm	● 0	---	---	---
Nickel	ppm	● <1	---	---	---
Titanium	ppm	● 0	---	---	---
Silver	ppm	<1	---	---	---
Manganese	ppm	● 2	---	---	---
Vanadium	ppm	0	---	---	---



ADDITIVES

Calcium	ppm	● 14	---	---	---
Magnesium	ppm	● 2	---	---	---
Zinc	ppm	22	---	---	---
Phosphorus	ppm	● 1648	---	---	---
Barium	ppm	21	---	---	---
Boron	ppm	● 116	---	---	---

Diagnosis

Confirm the source of the lubricant being utilized for top-up/fill. Resample at the next service interval to monitor. All component wear rates are normal. There is no indication of any contamination in the oil. Additive levels indicate the addition of a different brand, or type of oil. The condition of the oil is acceptable for the time in service.

Depot: RIC117RIC
 Unique No: 5708359
 Signed: Wes Davis
 Report Date: 08 Jan 2024



GRAPHS

