LIEBHERR

CONSTRUCTION EQUIPMENT

LIEBHERR LH30M 139284-1253 - Diesel Engine

Sample No: LH0241868

Oil Type: SHELL ROTELLA T4 15W40

PLE INFO	RMATION			
	LH0241868	LH0239949	LH0241859	
	31 Oct 2023	04 Sep 2023	06 Jul 2023	
	2739	2265	1668	
	0	0	0	
	Changed	Changed	Changed	
	NORMAL	NORMAL	NORMAL	
ONDITIO	N			
cSt	13.8	O 13.5	O 13.4	
%	76	75	77	
AMINA	TION			
		NEO	NEG	
, -				
	•	0 1	0 -	
%	75	73	72	
%	63	62	63	
%	0.0	0.0	NEG	
%	<1.0	<1.0	<1.0	
ppm	9	6	7	
ppm	2	O 4	O 2	
ppm	6	O 11	3	
	CSt % AMINA % % % % % % ppm ppm	31 Oct 2023 2739 0 Changed NORMAL ONDITION CSt	LH0241868	LH0241868 LH0239949 LH0241859 31 Oct 2023 04 Sep 2023 06 Jul 2023 2739 2265 1668 0 0 0 Changed Changed Changed NORMAL NORMAL NORMAL NORMAL NORMAL NORMAL PNDITION CSt ① 13.8 ② 13.5 ⑦ 75 ⑦ 77 AMINATION % NEG % ② 0 ② 0 ② 0 ③ 0 ③ 0 ③ 0 ③ 0 ③ 0

(O) WEAT					
WEA	R METALS				
Iron	ppm	3	4	4	
Copper	ppm	2	O 2	6	
Lead	ppm	0 <1	O <1	O <1	
Tin	ppm	0	O <1	O <1	
Aluminum	ppm	2	1	O 1	
Chromium	ppm	0	O 0	O <1	
Molybdenum	ppm	0 <1	O <1	5	
Nickel	ppm	0 <1	O 0	O <1	
Titanium	ppm	0	0	<1	
Silver	ppm	0	O <1	O 0	
Manganese	ppm	0	0	O <1	
Vanadium	ppm	0	0	0	

ADDITIVES								
Calcium	ppm	2246	O 2222	O 1973				
Magnesium	ppm	18	O 25	106				
Zinc	ppm	1151	O 1156	1100				
Phosphorus	ppm	975	957	944				
Barium	ppm	0	<1	<1				
Boron	ppm	105	95	9 4				



HUBERT & FILS 474 ROUTE 105 BOIS-FRANC, QC CA J9E 3A9 Contact: Eric Brisebois ericbrisebois99@gmail.com

T: F:

Diagnosis

Resample at the next service interval to monitor. All component wear rates are normal. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.

Depot:HUBBOIUnique No:5710055Signed:Kevin MarsonReport Date:17 Jan 2024

LIEBHERR







GRAPHS

