## LIEBHERR

**CONSTRUCTION EQUIPMENT** 

### LIEBHERR LH30M 139284-1253 - Front Left Wheel Hub

Sample No: LH0241876

Oil Type: LIEBHERR GEAR BASIC 90 LS

<b>5</b>					
U SAM	PLE INF	DRMATION			
Sample Number		LH0241876	LH0239957	LH0241864	
Sample Date		31 Oct 2023	04 Sep 2023	18 Apr 2023	
Machine Hours		2739	2265	1142	
Oil Hours		0	0	0	
Oil Changed		Changed	Changed	N/A	
Sample Status		NORMAL	NORMAL	NORMAL	
OILC	ONDITIO	ON			
Visc @ 40°C	cSt	<b>182</b>	O 182	<b>138</b>	
ii con					

CONTAMINATION							
Water	%	NEG	NEG	NEG			
Silicon	ppm	<b>0</b> 1	0 1	<b>4</b>			
Sodium	ppm	<b>4</b>	O 5	<b>10</b>			
Potassium	ppm	<b>1</b>	O 0	O <1			

₩E/	AR META	LS			
Iron	ppm	<b>26</b>	<b>2</b> 0	O 23	
Copper	ppm	<b>1</b>	<b>3</b>	O 12	
Lead	ppm	<b>0</b>	<b>0</b>	O <1	
Tin	ppm	0	0	0	
Aluminum	ppm	<1	O <1	O <1	
Chromium	ppm	<b>0</b>	O 0	O <1	
Molybdenum	ppm	<b>0</b>	<b>O</b> 0	O 0	
Nickel	ppm	<b>○</b> <1	O <1	O 0	
Titanium	ppm	0	0	0	
Silver	ppm	0	<1	0	
Manganese	ppm	<b>0</b>	<b>0</b>	O <1	
Vanadium	ppm	0	0	0	

vanadium	ppm	U	U	U		
ADDI						
ADDITIVES						
Calcium	ppm	67	114	722		
Magnesium	ppm	<b>O</b> <1	O <1	<b>2</b>		
Zinc	ppm	16	36	352		
Phosphorus	ppm	<b>2277</b>	2262	2142		
Barium	ppm	<b>0</b>	O <1	O 0		
Boron	ppm	<b>2</b>	<b>5</b>	<b>20</b>		



HUBERT & FILS 474 ROUTE 105 BOIS-FRANC, QC CA J9E 3A9 Contact: Eric Brisebois ericbrisebois99@gmail.com

T: F:

#### Diagnosis

Confirm the source of the lubricant being utilized for top-up/fill.
Resample at the next service interval to monitor. All component wear rates are normal. There is no indication of any contamination in the oil. Additive levels indicate the addition of a different brand, or type of oil. The condition of the oil is acceptable for the time in service.

Depot: HUBBOI
Unique No: 5710190
Signed: Kevin Marson
Report Date: 19 Jan 2024

# LIEBHERR







#### **GRAPHS**

