CONSTRUCTION EQUIPMENT

LIEBHERR L580 069442-1762 - Splitter Box

Sample No: LH0247600

Oil Type: **GEAR OIL SAE 80W90**





OIL CONDITION Visc @ 40°C cSt **178**

CONTAMINATION							
Water	%	NEG					
Silicon	ppm	() <1					
Sodium	ppm	() <1					
Potassium	ppm	() <1					

WEA	R METAL	S		
Iron	ppm	7 1	 	
Copper	ppm	○ <1	 	
Lead	ppm	0	 	
Tin	ppm	0	 	
Aluminum	ppm	1	 	
Chromium	ppm	○ <1	 	
Molybdenum	ppm	1	 	
Nickel	ppm	3	 	
Titanium	ppm	0	 	
Silver	ppm	0	 	
Manganese	ppm	0 <1	 	
Vanadium	ppm	0	 	

variadium	ppiii	U						
ADDITIVES								
Calcium	ppm	10						
Magnesium	ppm	2						
Zinc	ppm	74						
Phosphorus	ppm	1925						
Barium	ppm	0						
Boron	ppm	5						



HUBERT ET FILS INC

1012 CHEMIN DE PARC INDUSTRIEL BOIS-FRANC, QC CA J9E 3A9

Contact: Service Manager

T: F:

Diagnosis

Resample at the next service interval to monitor. The fluid was not specified, however, a fluid match indicates that this fluid is (GENERIC) GEAR OIL SAE 80W90. Please confirm.All component wear rates are normal. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.

Depot: HUB101BOI Unique No: 5710213 Signed: Kevin Marson **Report Date:** 16 Jan 2024

LIEBHERR







GRAPHS

