LIEBHERR

CONSTRUCTION EQUIPMENT

LIEBHERR R924 38847 - Splitter Box

Sample No: LH0280959

Oil Type: PETRO CANADA TRAXON 75W90 SYNTHETIC





CONTAMINATION								
Water	%	NEG	NEG	NEG				
Silicon	ppm	2	3	O 1				
Sodium	ppm	0 <1	O 2	O <1				
Potassium	ppm	0 <1	O <1	O <1				

WEA	AR METAI	.S			
Iron	ppm	7	○ 32	1 3	
Copper	ppm	 <1	O <1	O 0	
Lead	ppm	0	O 0	O 0	
Tin	ppm	0	O <1	O 0	
Aluminum	ppm	<1	O <1	O 0	
Chromium	ppm	0	O <1	0	
Molybdenum	ppm	0	O 0	O <1	
Nickel	ppm	O <1	O <1	O 0	
Titanium	ppm	0	0	0	
Silver	ppm	0	0	0	
Manganese	ppm	0	O <1	<1	
Vanadium	ppm	0	0	0	

variadium	ppm	U	U	U				
ADDITIVES								
Calcium	ppm	13	O 11	○ 51				
Magnesium	ppm	 <1	O <1	4				
Zinc	ppm	9	10	23				
Phosphorus	ppm	1266	2366	1301				
Barium	ppm	0	0	O				
Boron	ppm	332	1 3	318				



ECOWASTE INDUSTRIES LTD. 15111 WILLIAMS ROAD RICHMOND, BC CA V6W 1G9

Contact: Service Manager

T: (604)277-1410

F:

Diagnosis

Resample at the next service interval to monitor. All component wear rates are normal. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.

Depot: ECORIC
Unique No: 5720047
Signed: Wes Davis
Report Date: 24 Jan 2024


LIEBHERR

CONSTRUCTION EQUIPMENT





GRAPHS



Report Id: ECORIC [WCAMIS] 02610952 (Generated: 01/25/2024 16:50:33) Rev: 1

Contact/Location: Service Manager - ECORIC