

LIEBHERR

CONSTRUCTION EQUIPMENT



LIEBHERR LH26M 146752-1252 - Rear Right Wheel Hub

Sample No: LH0266476

Oil Type: {unknown}



J.M. CHAMPEAU INC.

491 ROUTE 253
SAINT-MALO, QC
CA J0B 2Y0

Contact: Bruno Champeau
bruno@champeau.com
T: (819)658-2244
F: (819)658-2128



SAMPLE INFORMATION

Sample Number	LH0266476	---	---	---
Sample Date	16 Oct 2023	---	---	---
Machine Hours	1053	---	---	---
Oil Hours	0	---	---	---
Oil Changed	N/A	---	---	---
Sample Status	NORMAL	---	---	---



OIL CONDITION

Visc @ 40°C	cSt	63.1	---	---	---
-------------	-----	------	-----	-----	-----



CONTAMINATION

Water	%	NEG	---	---	---
Silicon	ppm	5	---	---	---
Sodium	ppm	15	---	---	---
Potassium	ppm	1	---	---	---



WEAR METALS

Iron	ppm	219	---	---	---
Copper	ppm	30	---	---	---
Lead	ppm	<1	---	---	---
Tin	ppm	0	---	---	---
Aluminum	ppm	1	---	---	---
Chromium	ppm	<1	---	---	---
Molybdenum	ppm	0	---	---	---
Nickel	ppm	<1	---	---	---
Titanium	ppm	0	---	---	---
Silver	ppm	0	---	---	---
Manganese	ppm	2	---	---	---
Vanadium	ppm	0	---	---	---



ADDITIVES

Calcium	ppm	2781	---	---	---
Magnesium	ppm	7	---	---	---
Zinc	ppm	1264	---	---	---
Phosphorus	ppm	1173	---	---	---
Barium	ppm	0	---	---	---
Boron	ppm	76	---	---	---

Diagnosis

Échantillonner de nouveau l'équipement au prochain intervalle de vidange afin d'en surveiller la condition. Veuillez préciser la marque, le type et la viscosité de l'huile lors de votre prochain échantillon. Les taux d'usure de tous les composants sont normaux. Il n'y a aucun indice de contamination dans l'huile. L'état de l'huile est acceptable pour la durée de service.

Depot: CHASTM
Unique No: 5720719
Signed: Kevin Marson
Report Date: 26 Jan 2024



GRAPHS

