CONSTRUCTION EQUIPMENT

145586-1218 - Front Left Wheel Hub

Sample No: LH0269265

Oil Type: **GEAR OIL SAE 80W90**



OIL CONDITION Visc @ 40°C cSt **137**

CONTAMINATION								
Water	%	NEG						
Silicon	ppm	12						
Sodium	ppm	8						
Potassium	ppm	2						

(O) WE				
₩ WEA	R META	LS		
Iron	ppm	59	 	
Copper	ppm	3	 	
Lead	ppm	() <1	 	
Tin	ppm	O <1	 	
Aluminum	ppm	3	 	
Chromium	ppm	0 <1	 	
Molybdenum	ppm	() <1	 	
Nickel	ppm	○ <1	 	
Titanium	ppm	0	 	
Silver	ppm	0	 	
Manganese	ppm	1	 	
Vanadium	ppm	0	 	

variaulum	ppiii	U						
ADDITIVES								
Calcium	ppm	67						
Magnesium	ppm	3						
Zinc	ppm	42						
Phosphorus	ppm	1697						
Barium	ppm	0 <1						
Boron	ppm	75						





American Iron and Metal

10305 Metropolitaine Est, Garage porte 13 Montreal, QC CA H1B 1A1

Contact: Sebastien Liautaud sliautaud@aimrecyclinggroup.com

F:

Diagnosis

Resample at the next service interval to monitor. The fluid was not specified, however, a fluid match indicates that this fluid is (GENERIC) GEAR OIL SAE 80W90. Please confirm.

All component wear rates are normal. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.

Depot: **LACMON** Unique No: 5721668 Signed: Wes Davis **Report Date:** 31 Jan 2024

LIEBHERR







GRAPHS

