

# LIEBHERR

## CONSTRUCTION EQUIPMENT



### LIEBHERR A910 147124-1837 - Front Left Wheel Hub

Sample No: LH0279086

Oil Type: PETRO CANADA TRAXON SYNTHETIC MTF 75W80



Entreprises S. Besner Inc.

650 Route 201

Saint-Clet, QC

CA J0P 1S0

Contact: Tristan

Tristan@entreprisesbesner.com

T:

F:



#### SAMPLE INFORMATION

Sample Number	LH0279086	---	---	---
Sample Date	02 Feb 2024	---	---	---
Machine Hours	0	---	---	---
Oil Hours	0	---	---	---
Oil Changed	Changed	---	---	---
Sample Status	ATTENTION	---	---	---



#### OIL CONDITION

Visc @ 40°C	cSt	82.6	---	---	---
-------------	-----	------	-----	-----	-----



#### CONTAMINATION

Water	%	NEG	---	---	---
Silicon	ppm	50	---	---	---
Sodium	ppm	4	---	---	---
Potassium	ppm	6	---	---	---



#### WEAR METALS

Iron	ppm	154	---	---	---
Copper	ppm	37	---	---	---
Lead	ppm	1	---	---	---
Tin	ppm	0	---	---	---
Aluminum	ppm	5	---	---	---
Chromium	ppm	2	---	---	---
Molybdenum	ppm	0	---	---	---
Nickel	ppm	<1	---	---	---
Titanium	ppm	5	---	---	---
Silver	ppm	0	---	---	---
Manganese	ppm	2	---	---	---
Vanadium	ppm	0	---	---	---



#### ADDITIVES

Calcium	ppm	722	---	---	---
Magnesium	ppm	4	---	---	---
Zinc	ppm	1471	---	---	---
Phosphorus	ppm	699	---	---	---
Barium	ppm	4	---	---	---
Boron	ppm	95	---	---	---

#### Diagnosis

Confirmez la source du lubrifiant utilisé pour l'appoint/remplissage. Échantillonner de nouveau l'équipement au prochain intervalle de vidange afin d'en surveiller la condition. Les taux d'usure de tous les composants sont normaux. Il n'y a aucun indice de contamination dans l'huile. Les niveaux d'additifs indiquent l'ajout d'une autre marque ou d'un autre type d'huile. La viscosité de l'échantillon se situe dans la portée de l'SAE 30; nous vous conseillons de vérifier. L'état de l'huile est acceptable pour la durée de service.

Depot: ENT650STC

Unique No: 5722569

Signed: Bill Quesnel

Report Date: 05 Feb 2024



### GRAPHS

