LIEBHERR

CONSTRUCTION EQUIPMENT

[[597382]] LIEBHERR LH60M 143114-1217 - Splitter Box

Sample No: LH0280953
Oil Type: SAE 75W90

5							
SAMPLEINFORMATION							
Sample Number		LH0280953					
Sample Date		06 Feb 2024					
Machine Hours		2907					
Oil Hours		0					
Oil Changed		Changed					
Sample Status		NORMAL					
A							

OII	CONDITIO	N		
Visc @ 40°C	cSt	154	 	

CONTAMINATION							
Water	%	NEG					
Silicon	ppm	1					
Sodium	ppm	2					
Potassium	ppm	6					

₩EA	R META	LS		
Iron	ppm	22	 	
Copper	ppm	4	 	
Lead	ppm	○ <1	 	
Tin	ppm	0	 	
Aluminum	ppm	○ <1	 	
Chromium	ppm	0	 	
Molybdenum	ppm	1	 	
Nickel	ppm	0	 	
Titanium	ppm	0	 	
Silver	ppm	0	 	
Manganese	ppm	0	 	
Vanadium	ppm	0	 	

variadium	ppm	U					
ADDITIVES							
Calcium	ppm	135					
Magnesium	ppm	2					
Zinc	ppm	103					
Phosphorus	ppm	1430					
Barium	ppm	0					
Boron	ppm	1					



INLAND STEEL PRODUCTS INC.

1009 37 AVENUE LLOYDMINSTER, SK CA S9V 1K5

Contact: Service Manager

T: F:

Diagnosis

Resample at the next service interval to monitor. All component wear rates are normal. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.

Depot: INLLLO
Unique No: 5723385
Signed: Wes Davis
Report Date: 08 Feb 2024

LIEBHERR

CONSTRUCTION EQUIPMENT





GRAPHS

