LIEBHERR

CONSTRUCTION EQUIPMENT

134511 - Diesel Engine



SAMPLEINFO	PRMATION		
Sample Number	LH0284963	 	
Sample Date	08 Feb 2024	 	
Machine Hours	7000	 	
Oil Hours	0	 	
Oil Changed	Changed	 	
Sample Status	NORMAL	 	

ouripio otatas		HOHIMAL		
OIL CO	ONDITION			
Visc @ 100°C	cSt	13.2	 	
Oxidation (PA)	%	65	 	

CONTAMINATION					
Water	%	NEG			
Soot %	%	0			
Nitration (PA)	%	71			
Sulfation (PA)	%	52			
Glycol	%	NEG			
Fuel	%	<1.0			
Silicon	ppm	6			
Sodium	ppm	2			
Potassium	mag				

WEA WEA	R META	LS		
Iron	ppm	3	 	
Copper	ppm	2	 	
Lead	ppm	○ <1	 	
Tin	ppm	0	 	
Aluminum	ppm	2	 	
Chromium	ppm	0 <1	 	
Molybdenum	ppm	57	 	
Nickel	ppm	() <1	 	
Titanium	ppm	0	 	
Silver	ppm	0	 	
Manganese	ppm	0	 	
Vanadium	ppm	0	 	

Calcium ppm 1096 Magnesium ppm 933 Zinc ppm 1172	
Zinc ppm 0 1172	
Discourse and the same of the	
Phosphorus ppm 990	
Barium ppm 0	
Boron ppm 3	



LIEBHERR CANADA LTD. 1015 SUTTON DRIVE BURLINGTON, ON CA L7L 5Z8 Contact: Joseph Rodgers

joseph.rodgers@liebherr.com

F: (905)319-6622

Diagnosis

Resample at the next service interval to monitor. The fluid was not specified, however, a fluid match indicates that this fluid is (GENERIC) DIESEL ENGINE OIL SAE 40. Please confirm.

All component wear rates are normal. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.

Depot: LIEMIS
Unique No: 5723698
Signed: Wes Davis
Report Date: 09 Feb 2024

LIEBHERR CONSTRUCTION FOUNDMENT





GRAPHS

