

LIEBHERR LH60M 145111-1217 - Front Left Wheel Hub

Sample No: LH0285006

Oil Type: GEAR OIL SAE 80W90

SAMPLE INFORMATION

Sample Number	LH0285006	LH0247465	LH0261406	
Sample Date	12 Feb 2024	20 Jun 2023	27 Apr 2023	
Machine Hours	2972	1188	558	
Oil Hours	0	0	0	
Oil Changed	Changed	Changed	Changed	
Sample Status	NORMAL	NORMAL	NORMAL	
OIL CONDITI	ION			
Visc @ 40°C cSt	91.5	0 116	0 152	

	NTAMINA	TION			
Water	%	NEG	NEG	NEG	
Silicon	ppm	04	○ <1	○ 5	
Sodium	ppm	○ <1	2	5	
Potassium	ppm	○ <1	○ <1	0 1	

Ä					
WEA	R META	LS			
Iron	ppm	2	22	88	
Copper	ppm	0 5	07	0 12	
Lead	ppm	0 (0	◯ <1	
Tin	ppm	0 (0	0	
Aluminum	ppm	○ <1	◯ <1	2	
Chromium	ppm	0 (0	◯ <1	
Molybdenum	ppm	0 (0	0	
Nickel	ppm	◯ <1	0	◯ <1	
Titanium	ppm	0	0	◯ <1	
Silver	ppm	0	0	0	
Manganese	ppm	0 (◯ <1	3	
Vanadium	maa	0	0	0	

0

	ITIVES				
Calcium	ppm	3	0 11	18	
Magnesium	ppm	○ <1	0 2	2	
Zinc	ppm	6	0 16	47	
Phosphorus	ppm	696	0 1386	1626	
Barium	ppm	○ <1	27	103	
Boron	ppm	0 5	237	95	





RAM IRON AND METAL

60 Ashwarren Road TORONTO, ON CA M3J 1Z5 Contact: PETER RACCO PETER@RAMIRON.COM T: (416)630-4545 F: (416)630-5258

Diagnosis

Resample at the next service interval to monitor.All component wear rates are normal. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.

Depot:RAMUnique No:572Signed:WestReport Date:14 F

RAMTOR 5724540 Wes Davis 14 Feb 2024





GRAPHS

 \odot

