CONSTRUCTION EQUIPMENT

LIEBHERR LH60 152284 - Rear Right Wheel Hub

Sample No: LH0284967

Oil Type: **GEAR OIL SAE 80W90**

5					
SAMPLEINFORMATION					
Sample Number		LH0284967			
Sample Date		14 Feb 2024			
Machine Hours		596			
Oil Hours		0			
Oil Changed		N/A			
Sample Status		NORMAL			
OIL CONDITION					
Visc @ 40°C	cSt	138			

CONTAMINATION							
Water	%	NEG					
Silicon	ppm	4					
Sodium	ppm	5					
Potassium	ppm	1					

WF/	AR META	LS		
Iron	ppm	27	 	
Copper	ppm	5	 	
Lead	ppm	0	 	
Tin	ppm	0	 	
Aluminum	ppm	 <1	 	
Chromium	ppm	() <1	 	
Molybdenum	ppm	0	 	
Nickel	ppm	() <1	 	
Titanium	ppm	0	 	
Silver	ppm	0	 	
Manganese	ppm	○ <1	 	
Vanadium	ppm	0	 	

ADDITIVES						
Calcium	ppm	9				
Magnesium	ppm	2				
Zinc	ppm	11				
Phosphorus	ppm	1794				
Barium	ppm	4				
Boron	ppm	136				



LIEBHERR CANADA LTD. 1015 SUTTON DRIVE BURLINGTON, ON CA L7L 5Z8 Contact: Steve Lehto

steve.lehto@liebherr.com T: (905)319-9222

F: (905)319-6617

Diagnosis

Resample at the next service interval to monitor. The fluid was not specified, however, a fluid match indicates that this fluid is (GENERIC) GEAR OIL SAE 80W90. Please confirm.

All component wear rates are normal. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.

Depot: LIEMIS **Unique No:** 5733192 Signed: Wes Davis Report Date: 15 Feb 2024

Contact/Location: Steve Lehto - LIEMIS

LIEBHERR







GRAPHS

