CONSTRUCTION EQUIPMENT

152076 - Rear Differential

Sample No: LH0278773

Oil Type: **GEAR OIL SAE 80W90**





OIL CONDITION

Visc @ 40°C cSt **155**

CONTAMINATION									
Water	%	NEG							
Silicon	ppm	6							
Sodium	ppm	1							
Potassium	ppm	1							

WE!				
WE/	AR META	LS		
Iron	ppm	18	 	
Copper	ppm	6	 	
Lead	ppm	○ <1	 	
Tin	ppm	0	 	
Aluminum	ppm	<1	 	
Chromium	ppm	0	 	
Molybdenum	ppm	0	 	
Nickel	ppm	0	 	
Titanium	ppm	0	 	
Silver	ppm	0	 	
Manganese	ppm	 <1	 	
Vanadium	nnm	0	 	

vanadium	ppm	U							
ADDI									
ADDITIVES									
Calcium	ppm	127							
Magnesium	ppm	1							
Zinc	ppm	16							
Phosphorus	ppm	1492							
Barium	ppm	1							
Boron	ppm	24							





LIEBHERR CANADA LTD.

1015 SUTTON DRIVE BURLINGTON, ON CA L7L 5Z8

Contact: Steve Lehto steve.lehto@liebherr.com

T: (905)319-9222 F: (905)319-6617

Diagnosis

Resample at the next service interval to monitor. The fluid was not specified, however, a fluid match indicates that this fluid is (GENERIC) GEAR OIL SAE 80W90. Please confirm.

Please specify the component make and model with your next sample.All component wear rates are normal. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.

Depot: LIEMIS Unique No: 5733519 Signed: Wes Davis **Report Date:** 16 Feb 2024

Contact/Location: Steve Lehto - LIEMIS

LIEBHERR

CONSTRUCTION EQUIPMENT





GRAPHS

