**CONSTRUCTION EQUIPMENT** 

## **LIEBHERR R914 056971-1511 - Swing Drive**

Sample No: LH0284028

**OIL CONDITION** 

cSt

Visc @ 40°C

Water

Silicon

Sodium

Zinc

Barium

Boron

Phosphorus

Oil Type: PETRO CANADA TRAXON SYNTHETIC 75W90

180





**WEKA HOLDINGS LTD** 2754 WOODLAND DRIVE VANCOUVER, BC **CA V5N 3P8** Contact: Cam Turtle

T: F:

	-
	F

#### CONTAMINATION **NEG** ppm **11 7** ppm Potassium ppm **2**

WEA	R METALS			
Iron	ppm	<b>418</b>	 	
Copper	ppm	<b>83</b>	 	
Lead	ppm	<b>3</b>	 	
Tin	ppm	<b>8</b>	 	
Aluminum	ppm	<b>2</b>	 	
Chromium	ppm	<b>3</b>	 	
Molybdenum	ppm	<b>0</b>	 	
Nickel	ppm	<b>0</b> <1	 	
Titanium	ppm	0	 	
Silver	ppm	0	 	
Manganese	ppm	<b>4</b>	 	
Vanadium	ppm	0	 	

WEA	R METALS						
Iron	ppm	<b>418</b>					
Copper	ppm	<b>83</b>					
Lead	ppm	<b>3</b>					
Tin	ppm	<b>8</b>					
Aluminum	ppm	<b>2</b>					
Chromium	ppm	<b>3</b>					
Molybdenum	ppm	<b>0</b>					
Nickel	ppm	<b>O</b> <1					
Titanium	ppm	0					
Silver	ppm	0					
Manganese	ppm	<b>4</b>					
Vanadium	ppm	0					
ADDITIVES							
Calcium	ppm	<b>15</b>					
Magnesium	ppm	O 1					

### Diagnosis

Confirm the source of the lubricant being utilized for top-up/fill. Resample at the next service interval to monitor.All component wear rates are normal. There is no indication of any contamination in the oil. Additive levels indicate the addition of a different brand, or type of oil. The condition of the oil is acceptable for the time in service.

Depot: WEKVAN **Unique No:** 5733526 Signed: Wes Davis **Report Date:** 16 Feb 2024

**41** 

**8** 

2294

ppm

ppm

ppm

ppm

# LIEBHERR

CONSTRUCTION EQUIPMENT





#### **GRAPHS**

