LIEBHERR





[ZANCON FOUNDATIONS] LIEBHERR LB28 115549 - Left Track

Sample No: LH0216133

Chromium

Nickel

Silver

Titanium

Manganese

Vanadium

Calcium

Zinc

Barium

Boron

Magnesium

Phosphorus

Molybdenum

Oil Type: PETRO CANADA TRAXON 75W90 SYNTHETIC

4

0

2

0

0

2

8

1

19

964

0

ppm

ppm

ppm

ppm

ppm

ppm

ppm

ppm ppm

ppm

ppm

ppm

ppm

ADDITIVES

_				
U SAN	APLE INFO	DRMATION		
Sample Number		LH0216133	 	
Sample Date		14 Feb 2024	 	
Machine Hours		6734	 	
Oil Hours		0	 	
Oil Changed		Changed	 	
Sample Status		NORMAL	 	
A				
	CONDITIO	AN		
Visc @ 40°C	cSt	197	 	
and the second				
CON	ITAMINA	TION		
Water	%	NEG	 	
Silicon	ppm	0.8	 	
Sodium	ppm	3	 	
Potassium	ppm	2	 	
₩E/	AR META	LS		
Iron	ppm	O 264	 	
Copper	ppm	O 17	 	
Lead	ppm	0 <1	 	
Tin	ppm	0 <1	 	
Aluminum	ppm	2	 	



LIEBHERR CANADA LTD. 1015 SUTTON DRIVE BURLINGTON, ON CA L7L 5Z8

Contact: Steve Lehto steve.lehto@liebherr.com

T: (905)319-9222 F: (905)319-6617

Diagnosis

Confirm the source of the lubricant being utilized for top-up/fill.

Resample at the next service interval

to monitor.All component wear rates are normal. There is no indication of any contamination in the oil. Additive levels indicate the addition of a different brand, or type of oil. The condition of the oil is acceptable for the time in service.

Depot:LIEMISUnique No:5733532Signed:Wes DavisReport Date:20 Feb 2024

Contact/Location: Steve Lehto - LIEMIS

LIEBHERR

CONSTRUCTION EQUIPMENT





GRAPHS

