LIEBHERR

CONSTRUCTION EQUIPMENT

LIEBHERR LH40M 156305-1215 - Transmission (Manual)

Sample No: LH0278469

Oil Type: TDTO FLUID SAE 20

ā						
SAMPLEINFORMATION						
Sample Number	LH0278469					
Sample Date	20 Feb 2024					
Machine Hours	536					
Oil Hours	0					
Oil Changed	Changed					
Sample Status	NORMAL					
A						

OIL CC	NDITION				
40°C	cSt	60.0			
	OIL CO	OIL CONDITION	OIL CONDITION	OIL CONDITION	OIL CONDITION

CONT	TAMINAT	ION		
Water	%	NEG	 	
Silicon	ppm	5	 	
Sodium	ppm	44	 	
Potassium	ppm	3	 	

(O) WE	AR META	16		
AA EY	AR ME I A	LS		
Iron	ppm	16	 	
Copper	ppm	11	 	
Lead	ppm	() <1	 	
Tin	ppm	O <1	 	
Aluminum	ppm	3	 	
Chromium	ppm	O <1	 	
Molybdenum	ppm	0	 	
Nickel	ppm	O <1	 	
Titanium	ppm	0	 	
Silver	ppm	0	 	
Manganese	ppm	11	 	
Vanadium	ppm	0	 	

Calcium ppm 3189 Magnesium ppm 9 Zinc ppm 1084 Phosphorus ppm 1028 Barium ppm <1	ADD	ITIVES			
Zinc ppm 1084 Phosphorus ppm 1028 Barium ppm <1	Calcium	ppm	3189	 	
Phosphorus ppm ○ 1028 Barium ppm ○ <1	Magnesium	ppm	9	 	
Barium ppm () <1	Zinc	ppm	1084	 	
The Contract of the Contract o	Phosphorus	ppm	1028	 	
	Barium	ppm	○ <1	 	
Boron ppm 3	Boron	ppm	3	 	



Urban Mine
72 Rothwell Rd.
Winnipeg, MB
CA R3P 2H7
Contact: SERVICE

T: (204)774-0192 F:

Diagnosis

Resample at the next service interval to monitor. The fluid was not specified, however, a fluid match indicates that this fluid is (GENERIC) TDTO FLUID SAE 20. Please confirm.

All component wear rates are normal. There is no indication of any contamination in the fluid. The condition of the fluid is acceptable for the time in service.

Depot:URBWINUnique No:5734560Signed:Wes DavisReport Date:22 Feb 2024

LIEBHERR

CONSTRUCTION EQUIPMENT





GRAPHS

