## LIEBHERR

### **CONSTRUCTION EQUIPMENT**

### **LIEBHERR LH30M 112348 - Front Axle**

Sample No: LH0284127

Oil Type: PETRO CANADA TRAXON 75W90 SYNTHETIC



| CON       | CONTAMINATION |             |          |  |  |  |  |  |  |
|-----------|---------------|-------------|----------|--|--|--|--|--|--|
| Water     | %             | NEG         | NEG      |  |  |  |  |  |  |
| Silicon   | ppm           | <b>1</b>    | O 10     |  |  |  |  |  |  |
| Sodium    | ppm           | <b>O</b> <1 | <b>9</b> |  |  |  |  |  |  |
| Potassium | ppm           | <b>○</b> <1 | O 1      |  |  |  |  |  |  |
| -         |               |             |          |  |  |  |  |  |  |

| <b>WEA</b> | R METAL | .S          |            |      |
|------------|---------|-------------|------------|------|
| Iron       | ppm     | <b>3</b>    | <b>8</b>   | <br> |
| Copper     | ppm     | <b>○</b> <1 | O 3        | <br> |
| Lead       | ppm     | <1          | O <1       | <br> |
| Tin        | ppm     | <b>0</b>    | 0          | <br> |
| Aluminum   | ppm     | <1          | O 1        | <br> |
| Chromium   | ppm     | <b>0</b>    | O <1       | <br> |
| Molybdenum | ppm     | <b>0</b>    | <b>0</b>   | <br> |
| Nickel     | ppm     | <b>0</b>    | O <1       | <br> |
| Titanium   | ppm     | 0           | 0          | <br> |
| Silver     | ppm     | 0           | 6          | <br> |
| Manganese  | ppm     | <b>0</b>    | <b>O</b> 4 | <br> |
| Vanadium   | ppm     | 0           | 0          | <br> |
|            |         |             |            |      |

| variadium  | ppm | U           | U          |  |  |  |
|------------|-----|-------------|------------|--|--|--|
| 0          |     |             |            |  |  |  |
| ADDITIVES  |     |             |            |  |  |  |
| Calcium    | ppm | <b>150</b>  | 3483       |  |  |  |
| Magnesium  | ppm | <b>2</b>    | O 12       |  |  |  |
| Zinc       | ppm | <b>75</b>   | 1446       |  |  |  |
| Phosphorus | ppm | <b>1238</b> | O 1216     |  |  |  |
| Barium     | ppm | <b>0</b>    | O <1       |  |  |  |
| Boron      | ppm | <b>295</b>  | <b>104</b> |  |  |  |



#### Rypac Aluminum Recycling 11849 Tannery Road

Surrey, BC CA V3V 3W8 Contact: Craig Merritt rypac2@shaw.ca

T: F:

#### Diagnosis

Resample at the next service interval to monitor. All component wear rates are normal. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.

Depot: RYPSUR
Unique No: 5734570
Signed: Wes Davis
Report Date: 22 Feb 2024

# LIEBHERR

CONSTRUCTION EQUIPMENT





#### **GRAPHS**

