

## LIEBHERR LH30M 112348 - Transmission (Manual)

Sample No: LH0284129

يليم

Oil Type: PETRO CANADA 10W40

## SAMPLE INFORMATION

Sample Number		LH0284129	LH0260539		
Sample Date		12 Feb 2024	04 Jul 2023		
Machine Hours		5077	4130		
Oil Hours		0	0		
Oil Changed		Changed	Changed		
Sample Status		NORMAL	NORMAL		
<b>OIL CONDITION</b>					
Visc @ 40°C	cSt	<b>0</b> 61.4	57.6		

Water	%	NEG	NEG		
Silicon	ppm	<b>3</b>	03		
Sodium	ppm	0 12	23		
Potassium	ppm	0 2	03		

	R METAL	S		
Iron	ppm	0 14	0 16	 
Copper	ppm	0 29	0 42	 
Lead	ppm	01	01	 
Tin	ppm	01	01	 
Aluminum	ppm	0 2	0 4	 
Chromium	ppm	0	○ <1	 
Molybdenum	ppm	0 43	20	 
Nickel	ppm	◯ <1	○ <1	 
Titanium	ppm	0	0	 
Silver	ppm	0 (	0	 
Manganese	ppm	9	0 14	 
Vanadium	ppm	0	<1	 

٥ **ADDITIVES** Calcium 0 1739 ppm 2475 ○ 397 Magnesium ppm 0711 Zinc 0 1045 0 1115 ppm 0 1034 0 1034 Phosphorus ppm Barium 0 ppm ○ <1 Boron 0 60 ppm 0 28





## **Rypac Aluminum Recycling**

11849 Tannery Road Surrey, BC CA V3V 3W8 Contact: Craig Merritt rypac2@shaw.ca T: F:

## Diagnosis

Resample at the next service interval to monitor.All component wear rates are normal. There is no indication of any contamination in the fluid. The condition of the fluid is acceptable for the time in service.

Depot:	RYPSUR
Unique No:	5734576
Signed:	Kevin Marson
Report Date:	22 Feb 2024


Contact/Location: Craig Merritt - RYPSUR





GRAPHS

 $\overline{\mathbf{O}}$ 



Report Id: RYPSUR [WCAMIS] 02617466 (Generated: 02/22/2024 15:01:19) Rev: 1

Contact/Location: Craig Merritt - RYPSUR