LIEBHERR

CONSTRUCTION EQUIPMENT

LIEBHERR T60-9 022201-1709 - Rear Differential

Sample No: LH0228238

Oil Type: LIEBHERR GEAR MF 80W

a						
SAMPLE INFORMATION						
Sample Number		LH0228238				
Sample Date		20 Feb 2024				
Machine Hours		1045				
Oil Hours		0				
Oil Changed		Changed				
Sample Status		NORMAL				

- 10110.0					
OIL CO	NDITION				
40°C	cSt	51.9			
	OIL CO	OIL CONDITION	OIL CONDITION	OIL CONDITION	OIL CONDITION

CONTAMINATION						
Water	%	NEG				
Silicon	ppm	11				
Sodium	ppm	() <1				
Potassium	ppm	1				

₩EA	R METALS			
Iron	ppm	30	 	
Copper	ppm	3	 	
Lead	ppm	0	 	
Tin	ppm	0	 	
Aluminum	ppm	2	 	
Chromium	ppm	○ <1	 	
Molybdenum	ppm	0	 	
Nickel	ppm	○ <1	 	
Titanium	ppm	0	 	
Silver	ppm	<1	 	
Manganese	ppm	5	 	
Vanadium	ppm	0	 	

variaulum	ppiii	U				
ADDITIVES						
Calcium	ppm	3378				
Magnesium	ppm	13				
Zinc	ppm	1287				
Phosphorus	ppm	1312				
Barium	ppm	() <1				
Boron	ppm	94				



ECOWASTE INDUSTRIES

4 SPRUCE ST NEW WESTMINSTER, BC CA V3L 5G6

Contact: Service Manager

T: F:

Diagnosis

Resample at the next service interval to monitor. All component wear rates are normal. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.

Depot:ECONEWUnique No:5734578Signed:Wes DavisReport Date:22 Feb 2024

LIEBHERR

CONSTRUCTION EQUIPMENT





GRAPHS

