LIEBHERR

CONSTRUCTION EQUIPMENT

LIEBHERR LH40M 156305-1215 - Rear Left Wheel Hub

Sample No: LH0278477

Oil Type: GEAR OIL SAE 80W90

a						
SAMPLEINFORMATION						
Sample Number	LH0278477					
Sample Date	20 Feb 2024					
Machine Hours	536					
Oil Hours	0					
Oil Changed	Changed					
Sample Status	NORMAL					

	OIL CC	NDITION			
Visc @	40°C	cSt	141	 	

CON	MAATI	ATION		
Water	%	NEG	 	
Silicon	ppm	5	 	
Sodium	ppm	2	 	
Potassium	ppm	1	 	

WE/	AR META	16		
Iron	ppm	28	 	
Copper	ppm	5	 	
Lead	ppm	() <1	 	
Tin	ppm	0 0	 	
Aluminum	ppm	() <1	 	
Chromium	ppm	() <1	 	
Molybdenum	ppm	() <1	 	
Nickel	ppm	0 0	 	
Titanium	ppm	0 0	 	
Silver	ppm	0	 	
Manganese	ppm	() <1	 	
Vanadium	ppm	0	 	

ADDI	TIVES			
Calcium	ppm	134	 	
Magnesium	ppm	0 <1	 	
Zinc	ppm	21	 	
Phosphorus	ppm	1428	 	
Barium	ppm	1	 	
Boron	ppm	10	 	



Urban Mine
72 Rothwell Rd.
Winnipeg, MB
CA R3P 2H7
Contact: SERVICE

T: (204)774-0192 F:

Diagnosis

Resample at the next service interval to monitor. The fluid was not specified, however, a fluid match indicates that this fluid is (GENERIC) GEAR OIL SAE 80W90. Please confirm.

All component wear rates are normal. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.

Depot:URBWINUnique No:5734610Signed:Wes DavisReport Date:22 Feb 2024

LIEBHERR

CONSTRUCTION EQUIPMENT





GRAPHS

