

LIEBHERR

CONSTRUCTION EQUIPMENT



[(351064)] 122398-1216 - Rear Left Wheel Hub

Sample No: LH0281252

Oil Type: PETRO CANADA TRAXON 75W90 SYNTHETIC



SAMPLE INFORMATION

Sample Number	LH0281252	LH0202600	---	---
Sample Date	07 Feb 2024	20 Oct 2021	---	---
Machine Hours	5387	584	---	---
Oil Hours	0	0	---	---
Oil Changed	Changed	Changed	---	---
Sample Status	NORMAL	NORMAL	---	---

American Iron and Metal

75 Steel City Court
Hamilton, ON
CA L8H 3Y2
Contact: Heavy Equipment
hamiltonmobileassetmaintenance@aim-recycling.com
T: (905)547-5533
F: (905)544-5671



OIL CONDITION

Visc @ 40°C	cSt	172	● 148	---	---
-------------	-----	-----	-------	-----	-----



CONTAMINATION

Water	%	NEG	NEG	---	---
Silicon	ppm	● 5	● 9	---	---
Sodium	ppm	● 1	● 4	---	---
Potassium	ppm	● <1	● 1	---	---



WEAR METALS

Iron	ppm	● 27	● 21	---	---
Copper	ppm	● 8	● 32	---	---
Lead	ppm	● <1	● <1	---	---
Tin	ppm	● 0	● 0	---	---
Aluminum	ppm	● <1	● <1	---	---
Chromium	ppm	● 0	● <1	---	---
Molybdenum	ppm	● 0	● 2	---	---
Nickel	ppm	● <1	● <1	---	---
Titanium	ppm	● 0	0	---	---
Silver	ppm	● 0	<1	---	---
Manganese	ppm	● 0	● <1	---	---
Vanadium	ppm	0	0	---	---



ADDITIVES

Calcium	ppm	● 8	● 192	---	---
Magnesium	ppm	● 3	● 2	---	---
Zinc	ppm	● 13	● 50	---	---
Phosphorus	ppm	2134	● 2117	---	---
Barium	ppm	● 0	● 1	---	---
Boron	ppm	45	● 8	---	---

Diagnosis

Confirm the source of the lubricant being utilized for top-up/fill. Resample at the next service interval to monitor. All component wear rates are normal. There is no indication of any contamination in the oil. Additive levels indicate the addition of a different brand, or type of oil. The condition of the oil is acceptable for the time in service.

Depot: AMEHAM
Unique No: 5736467
Signed: Wes Davis
Report Date: 01 Mar 2024



GRAPHS

