## LIEBHERR

**CONSTRUCTION EQUIPMENT** 

### [(351064)] 122398-1216 - Front Right Wheel Hub

Sample No: LH0281251

Oil Type: PETRO CANADA TRAXON 75W90 SYNTHETIC

<b>a</b>							
U SAN	APLE INF	ORMATION					
Sample Number		LH0281251	LH0202598				
Sample Date		07 Feb 2024	20 Oct 2021				
Machine Hours		5387	584				
Oil Hours		0	0				
Oil Changed		Changed	Changed				
Sample Status		NORMAL	NORMAL				
OIL CONDITION							
Visc @ 40°C	cSt	<b>149</b>	O 144				
2 h							
CONTAMINATION							
Water	%	NEG	NEG				
Silicon	ppm	<b>6</b>	O 12				
Sodium	ppm	O 4	0.6				

Potassium	ppm	<b>0</b> <1	O 2					
WEAR METALS								
Iron	ppm	<b>53</b>	○ 34					
Copper	ppm	<b>3</b>	<b>10</b>					
Lead	ppm	<b>()</b> <1	O <1					
Tin	ppm	<b>0</b>	0					
Aluminum	ppm	<b>0</b> <1	O 2					
Chromium	ppm	<b>()</b> <1	O <1					
Molybdenum	ppm	<b>0</b>	O 2					
Nickel	ppm	<b>0</b> <1	O <1					
Titanium	ppm	<b>0</b>	0					
Silver	ppm	<b>0</b>	<1					
Manganese	ppm	<b>()</b> <1	<b>1</b>					
Vanadium	ppm	0	0					

vanadium	ppm	U	0				
0							
ADDITIVES							
Calcium	ppm	<b>19</b>	O 172				
Magnesium	ppm	<b>2</b>	<b>3</b>				
Zinc	ppm	<b>9</b>	O 51				
Phosphorus	ppm	2012	O 2019				
Barium	ppm	<b>0</b>	O <1				
Boron	ppm	71	O 19				



#### **American Iron and Metal**

75 Steel City Court Hamilton, ON CA L8H 3Y2

Contact: Heavy Equipment

hamiltonmobileassetmaintenance@aim-recycling.com

T: (905)547-5533 F: (905)544-5671

#### Diagnosis

Confirm the source of the lubricant being utilized for top-up/fill.

Resample at the next service interval to monitor. All component wear rates are normal. There is no indication of any contamination in the oil. Additive levels indicate the addition of a different brand, or type of oil. The condition of the oil is acceptable for the time in service.

Depot: AMEHAM
Unique No: 5736468
Signed: Wes Davis
Report Date: 01 Mar 2024

# LIEBHERR







#### **GRAPHS**

