LIEBHERR

CONSTRUCTION EQUIPMENT

LIEBHERR LH50 156991 - Hydraulic System

Sample No: LH0285076
Oil Type: {unknown}



OIL CONDITION							

CONTAMINATION						
Water	%	NEG				
Particles >4µm		2595				
Particles >6µm		518				
Particles >14µm		28				
ISO 4406:1999 (c)		19/16/12				
Silicon	ppm	2				
Sodium	ppm	() <1				
Potassium	ppm	1				

(O) WEAT				
₩ WEA	R METALS			
		_		
Iron	ppm	17	 	
Copper	ppm	2	 	
Lead	ppm	0	 	
Tin	ppm	0	 	
Aluminum	ppm	() <1	 	
Chromium	ppm	0	 	
Molybdenum	ppm	0	 	
Nickel	ppm	0 <1	 	
Titanium	ppm	0	 	
Silver	ppm	0	 	
Manganese	ppm	0	 	
Vanadium	ppm	0	 	

Variadiani	ppiii	•			
ADDITIVES					
Calcium	ppm	788			
Magnesium	ppm	5			
Zinc	ppm	766			
Phosphorus	ppm	644			
Barium	ppm	0			
Boron	ppm	<1			





LIEBHERR CANADA LTD. 1015 SUTTON DRIVE BURLINGTON, ON CA L7L 5Z8

Contact: Steve Lehto steve.lehto@liebherr.com

T: (905)319-9222 F: (905)319-6617

Diagnosis

Resample at the next service interval to monitor. Please specify the brand, type, and viscosity of the oil on your next sample.All component wear rates are normal. The system cleanliness is acceptable for your target ISO 4406 cleanliness code. The system and fluid cleanliness is acceptable. The condition of the oil is acceptable for the time in service.

Depot: LIEMIS
Unique No: 5737067
Signed: Wes Davis
Report Date: 05 Mar 2024

Contact/Location: Steve Lehto - LIEMIS

CONSTRUCTION EQUIPMENT





GRAPHS

