LIEBHERR

CONSTRUCTION EQUIPMENT

LIEBHERR LH50 156991 - Splitter Box

Sample No: LH0285075

Oil Type: GEAR OIL SAE 80W90



CONT	CONTAMINATION									
Water	%	NEG								
Silicon	ppm	0 <1								
Sodium	ppm	2								
Potassium	ppm	2								

WEA	R METALS			
Iron	ppm	19	 	
Copper	ppm	2	 	
Lead	ppm	0	 	
Tin	ppm	0	 	
Aluminum	ppm	0 <1	 	
Chromium	ppm	0	 	
Molybdenum	ppm	0	 	
Nickel	ppm	○ <1	 	
Titanium	ppm	0	 	
Silver	ppm	0	 	
Manganese	ppm	() <1	 	
Vanadium	ppm	0	 	

ADDITIVES							
Calcium	ppm	26					
Magnesium	ppm	2					
Zinc	ppm	27					
Phosphorus	ppm	1299					
Barium	ppm	() <1					
Boron	ppm	○ <1					



LIEBHERR CANADA LTD.
1015 SUTTON DRIVE
BURLINGTON, ON
CA L7L 5Z8
Contact: Steve Lehto
steve.lehto@liebherr.com

T: (905)319-9222 F: (905)319-6617

Diagnosis

Resample at the next service interval to monitor. The fluid was not specified, however, a fluid match indicates that this fluid is (GENERIC) GEAR OIL SAE 80W90. Please confirm.

All component wear rates are normal. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.

Depot:LIEMISUnique No:5737078Signed:Wes DavisReport Date:05 Mar 2024

LIEBHERR







GRAPHS

