# LIEBHERR

**CONSTRUCTION EQUIPMENT** 

## LIEBHERR LH50 156991 - Rear Right Wheel Hub

Sample No: LH0285080

Nickel

Silver

Titanium

Manganese

Vanadium

Calcium

Zinc

Barium

Boron

Magnesium

Phosphorus

ppm

ppm

ppm

ppm

ppm

mqq

ppm

ppm

ppm

ppm

ppm

**ADDITIVES** 

 $\bigcirc$  0

0

0

0<1

**170** 

0<1

**26** 

**2** 

**8** 

**1490** 

Oil Type: GEAR OIL SAE 80W90

PLE INFO	RMATION			
	LH0285080	LH0285074		
	04 Mar 2024	04 Mar 2024		
	1005	1005		
	0	0		
	Changed	Changed		
	NORMAL			
ONDITIO	N			
cSt	<b>137</b>	O 173		
<b>TAMINA</b>	TION			
%	NEG	NEG		
ppm	<b>4</b>	O 13		
ppm	<b>1</b>	<b>3</b>		
ppm	<b>1</b>	O 2		
ppm	<u> </u>			
ppm				
ppm		_		
ppm	<b>○</b> <1	O 4		
ppm	<b>○</b> <1	<b>3</b>		
	<b>0</b> <1			
	ONDITIO cSt  TAMINAT % ppm ppm ppm ppm ppm ppm ppm ppm ppm p	04 Mar 2024 1005 0 Changed NORMAL  ONDITION CSt	LH0285080  LH0285074  04 Mar 2024  1005  1005  0  Changed  NORMAL   CNDITION  cSt  137  173  CSt  NEG  ppm  4  ppm  1  ppm  1  2  RMETALS  ppm  18  ppm  10  256  ppm  01  7  ppm  01  7  ppm  01  25  ppm  01  01  02  01  01  01  01  01  01  01	LH0285080   LH0285074       04 Mar 2024   04 Mar 2024       1005   1005       0

35

12

22

2230



### **LIEBHERR CANADA LTD.** 1015 SUTTON DRIVE BURLINGTON, ON

CA L7L 5Z8

Contact: Steve Lehto steve.lehto@liebherr.com

T: (905)319-9222 F: (905)319-6617

#### Diagnosis

Resample at the next service interval to monitor. The fluid was not specified, however, a fluid match indicates that this fluid is (GENERIC) GEAR OIL SAE 80W90. Please confirm.

All component wear rates are normal. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.

Depot: LIEMIS
Unique No: 5737081
Signed: Wes Davis
Report Date: 05 Mar 2024

# LIEBHERR

CONSTRUCTION EQUIPMENT





### **GRAPHS**

