**CONSTRUCTION EQUIPMENT** 

## LIEBHERR LH40M 155749-1215 - Splitter Box

Sample No: LH0286912

Oil Type: **GEAR OIL SAE 80W90** 



Cumpic	Otalas		HOIIMAL		
0	OIL CO	<b>ONDITION</b>			
Visc @	40°C	cSt	<b>188</b>	 	

	CONTAMINATION							
Water	%	NEG						
Silicon	ppm	<b>○</b> <1						
Sodium	ppm	<b>2</b>						
Potassium	ppm	<b>2</b>						

₩E/	AR META	LS		
Iron	ppm	<b>22</b>	 	
Copper	ppm	<b>O</b> <1	 	
Lead	ppm	<b>○</b> <1	 	
Tin	ppm	<b>0</b>	 	
Aluminum	ppm	<b>()</b> <1	 	
Chromium	ppm	<b>0</b>	 	
Molybdenum	ppm	<b>0</b>	 	
Nickel	ppm	<b>○</b> <1	 	
Titanium	ppm	0	 	
Silver	ppm	0	 	
Manganese	ppm	<b></b> <1	 	
Vanadium	ppm	0	 	

<b>ADDITIVES</b>						
Calcium	ppm	<b>12</b>				
Magnesium	ppm	<b>3</b>				
Zinc	ppm	<b>16</b>				
Phosphorus	ppm	<b>1600</b>				
Barium	ppm	<b>0</b>				
Boron	ppm	<b>0</b> <1				
Barium	ppm	0				



#### **MOFFATT SCRAP IRON & METAL INC.**

9620 GUELPH LINE CAMPBELLVILLE, ON CA LOP 1B0

Contact: Paul Brochu

maintenance@moffatscrapiron.ca

T: (905)854-2792 F: (905)854-1225

#### Diagnosis

Resample at the next service interval to monitor. The fluid was not specified, however, a fluid match indicates that this fluid is (GENERIC) GEAR OIL SAE 80W90. Please confirm.All component wear rates are normal. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.

Depot: **MOFMOF** Unique No: 5746315 Signed: Kevin Marson **Report Date:** 11 Mar 2024

# LIEBHERR

CONSTRUCTION EQUIPMENT





### **GRAPHS**

