LIEBHERR

CONSTRUCTION EQUIPMENT



[MODERN] LIEBHERR L586 74609 - Rear Left Wheel Hub

Sample No: LH0284813

Oil Type: LIEBHERR GEAR BASIC 90 LS

a					
U SAMI	PLE INF	DRMATION			
Sample Number		LH0284813	LH0277036		
Sample Date		02 Mar 2024	21 Oct 2023		
Machine Hours		11699	1117		
Oil Hours		0	0		
Oil Changed		N/A	Changed		
Sample Status		NORMAL	NORMAL		
OIL C	ONDITIO	N			
Visc @ 40°C	cSt	184	189		
CONTAMINATION					

CONT	CONTAMINATION						
Water	%	NEG	NEG				
Silicon	ppm	11	○ 32				
Sodium	ppm	3	10				
Potassium	ppm	1	O <1				

Ø WE		_		
WEA	IR METAL	.5		
Iron	ppm	183	O 515	
Copper	ppm	125	O 140	
Lead	ppm	3	4	
Tin	ppm	6	O 11	
Aluminum	ppm	1	O 2	
Chromium	ppm	1	O 3	
Molybdenum	ppm	0	0	
Nickel	ppm	○ <1	O <1	
Titanium	ppm	0	0	
Silver	ppm	0	<1	
Manganese	ppm	10	34	
Vanadium	ppm	0	0	

II I	T.F.					
ADDITIVES						
Calcium	ppm	⊚ 8	O 13			
Magnesium	ppm	2	6			
Zinc	ppm	46	O 121			
Phosphorus	ppm	2354	O 2269			
Barium	ppm	0	O <1			
Boron	ppm	1	O 4			



LIEBHERR CANADA

10 LYNDS AVENUE MONCTON, NB CA E1H 3K2 Contact: Bryan Wood

Contact: Bryan Wood bryan.wood@liebherr.com

T:

F: (506)854-2940

Diagnosis

Resample at the next service interval to monitor. All component wear rates are normal. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.

Depot:LIEMONUnique No:5747931Signed:Wes DavisReport Date:19 Mar 2024

LIEBHERR

CONSTRUCTION EQUIPMENT





GRAPHS

