# LIEBHERR

**CONSTRUCTION EQUIPMENT** 

### LIEBHERR LH30M 145272-1253 - Rear Left Wheel Hub

Sample No: LH

Oil Type: GEAR OIL LS 80W90

_							
SAMPLEINFORMATION							
Sample Number	LH	LH0250158	LH0250174				
Sample Date	14 Mar 2024	08 Sep 2023	05 Jun 2023				
Machine Hours	2004	1004	500				
Oil Hours	0	0	500				
Oil Changed	Changed	Changed	Changed				
Sample Status	NORMAL	NORMAL	NORMAL				

Campio Clarac		HOIMAL	140111111111	140111111111	
OILCO	<b>ONDITION</b>				
Visc @ 40°C	cSt	<b>180</b>	<b>139</b>	65.0	

CON	NTAMIN!	ATION			
Water	%	NEG	NEG	NEG	
Silicon	ppm	<b>3</b>	02	<b>8</b>	
Sodium	ppm	<b>2</b>	O 11	<b>16</b>	
Potassium	ppm	<b>2</b>	O <1	O <1	

WEA	R METALS				
Iron	ppm	<b>22</b>	O 19	O 10	
Copper	ppm	<b>0</b> <1	O 12	<b>4</b>	
Lead	ppm	<b>0</b> 0	O <1	0	
Tin	ppm	0	0	0	
Aluminum	ppm	<b>0</b> <1	O <1	O <1	
Chromium	ppm	<b>0</b>	O <1	0	
Molybdenum	ppm	<b>0</b>	O 0	0	
Nickel	ppm	<b>○</b> <1	O <1	O <1	
Titanium	ppm	0	0	<1	
Silver	ppm	0	0	0	
Manganese	ppm	<b>○</b> <1	O <1	2	
Vanadium	ppm	0	0	0	

ADDITIVES						
Calcium	ppm	<b>98</b>	1017	3931		
Magnesium	ppm	<b>1</b>	<b>4</b>	11		
Zinc	ppm	<b>28</b>	453	1509		
Phosphorus	ppm	<b>2382</b>	O 1992	1293		
Barium	ppm	<b>0</b>	O 0	<1		
Boron	ppm	<b>3</b>	19	104		



#### Industrial Metals 550 Messier St. Winnipeg, MB CA R2J 0G5

Contact: Service Manager

T: F:

#### Diagnosis

Resample at the next service interval to monitor. All component wear rates are normal. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.

Depot:IND550WINUnique No:5748256Signed:Wes DavisReport Date:19 Mar 2024

## LIEBHERR

CONSTRUCTION EQUIPMENT





#### **GRAPHS**

