LIEBHERR

CONSTRUCTION EQUIPMENT

LIEBHERR LH30M 145272-1253 - Rear Differential

Sample No: LH

Oil Type: GEAR OIL SAE 80W90

5							
SAMPLEINFORMATION							
Sample Number	LH	LH0250160	LH0250172				
Sample Date	14 Mar 2024	08 Sep 2023	05 Jun 2023				
Machine Hours	2004	1004	500				
Oil Hours	0	0	500				
Oil Changed	Changed	Changed	Changed				
Sample Status	NORMAL	NORMAL	NORMAL				
A							

Jampic	Otatas		HOHIWAL	TAOT HALL	TYOT TIVIT TE	
A						
(OIL CO	NDITION				
/isc @	40°C	cSt	181		○ 64.7	

CONTAMINATION							
Water	%	NEG	NEG	NEG			
Silicon	ppm	3	O 2	8			
Sodium	ppm	2	O 2	15			
Potassium	ppm	0 <1	O <1	1			

₩EA	R METALS				
Iron	ppm	22	O 4	O 10	
Copper	ppm	0 <1	0 <1	4	
Lead	ppm	0 0	O <1	O <1	
Tin	ppm	0	0	0	
Aluminum	ppm	○ <1	O <1	O <1	
Chromium	ppm	○ <1	0	O <1	
Molybdenum	ppm	0	0	O 0	
Nickel	ppm	○ <1	O <1	O <1	
Titanium	ppm	0	0	<1	
Silver	ppm	0	0	0	
Manganese	ppm	○ <1	O <1	2	
Vanadium	ppm	0	0	0	

variaululli	ppiii	U	U	U			
0							
ADDITIVES							
Calcium	ppm	98	O 195	○ 3779			
Magnesium	ppm	2	O 1	O 11			
Zinc	ppm	28	88	O 1426			
Phosphorus	ppm	2376	O 2272	O 1224			
Barium	ppm	0	0	O <1			
Boron	ppm	2	5	99			



Industrial Metals 550 Messier St. Winnipeg, MB CA R2J 0G5

Contact: Service Manager

T: F:

Diagnosis

Resample at the next service interval to monitor. All component wear rates are normal. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.

Depot:IND550WINUnique No:5748258Signed:Wes DavisReport Date:19 Mar 2024

LIEBHERR

CONSTRUCTION EQUIPMENT





GRAPHS

