LIEBHERR

CONSTRUCTION EQUIPMENT

LIEBHERR LH50M 132404-1216 - Front Left Wheel Hub

Sample No: LH0209254

Oil Type: GEAR OIL SAE 75W90

5				
SAMPL	E INFORMATION			
Sample Number	LH0209254	LH0223409	LH0209282	
Sample Date	15 Mar 2024	20 Oct 2023	24 Mar 2023	
Machine Hours	12925	11209	8500	
Oil Hours	0	0	0	
Oil Changed	Changed	Changed	Changed	
Sample Status	NORMAL		NORMAL	
OIL COI	NOITION			
Visc @ 40°C	St 92.8	139	○ 89.8	

CONTAMINATION						
Water	%	NEG	NEG	NEG		
Silicon	ppm	3	O 2	O 24		
Sodium	ppm	4	6	O 2		
Potassium	ppm	10	0 1	O <1		

WEA	R METAL	S			
Iron	ppm	46	○ 30	O 27	
Copper	ppm	4	O 15	4	
Lead	ppm	0	0	O <1	
Tin	ppm	0	O 0	0	
Aluminum	ppm	0	O <1	O 0	
Chromium	ppm	0	0	O 0	
Molybdenum	ppm	0	0	0	
Nickel	ppm	0	O 0	0	
Titanium	ppm	0	0	0	
Silver	ppm	0	0	0	
Manganese	ppm	0	0	O <1	
Vanadium	ppm	0	0	0	

vanadium	ppm	U	U	U		
ADDITIVES						
Calcium	ppm	12	O 47	O 13		
Magnesium	ppm	O <1	O <1	0		
Zinc	ppm	13	O 22	1 4		
Phosphorus	ppm	1069	1956	1110		
Barium	ppm	0	0	0		
Boron	ppm	153	4 7	146		



HUBERT & FILS
474 ROUTE 105
BOIS-FRANC, QC
CA J9E 3A9
Contact: Eric Brisebois
ericbrisebois99@gmail.com
T:

F:

Diagnosis

Resample at the next service interval to monitor. All component wear rates are normal. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.

Depot:HUBBOIUnique No:5750496Signed:Wes DavisReport Date:28 Mar 2024







GRAPHS

