LIEBHERR

CONSTRUCTION EQUIPMENT

LIEBHERR LH50M 132404-1216 - Front Right Wheel Hub

Sample No: LH

Oil Type: IRVING HDH SAE 75W90

5				
SAN	APLE INF	ORMATION		
Sample Number	r	LH	LH0209283	
Sample Date		02 Feb 2024	24 Mar 2023	
Machine Hours		12428	8511	
Oil Hours		0	0	
Oil Changed		Changed	N/A	
Sample Status		NORMAL	NORMAL	
OIL	CONDITI	ON		
Visc @ 40°C	cSt	92.5	○ 81.7	
- 1 min				
CON	IT A SAIRI	ATION		

CONTAMINATION								
Water	%	NEG	NEG					
Silicon	ppm	3	3					
Sodium	ppm	1	O 2					
Potassium	ppm	○ <1	0					

(O) WE				
₩ WEA	AR META	LS		
Iron	ppm	29	O 29	
Copper	ppm	4	0 8	
Lead	ppm	0	O 0	
Tin	ppm	0	O 0	
Aluminum	ppm	0	O <1	
Chromium	ppm	0	O 0	
Molybdenum	ppm	0	0	
Nickel	ppm	0	O <1	
Titanium	ppm	0	0	
Silver	ppm	0	0	
Manganese	ppm	0	O <1	
Vanadium	ppm	0	0	

Vanadium	ppm	0	0				
ADDITIVES							
Calcium	ppm	21	85				
Magnesium	ppm	O <1	O <1				
Zinc	ppm	17	O 81				
Phosphorus	ppm	1115	O 1036				
Barium	ppm	0	O 0				
Boron	ppm	147	O 127				



HUBERT & FILS
474 ROUTE 105
BOIS-FRANC, QC
CA J9E 3A9
Contact: Eric Brisebois
ericbrisebois99@gmail.com
T:

1: F:

Diagnosis

Resample at the next service interval to monitor. All component wear rates are normal. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.

Depot:HUBBOIUnique No:5750514Signed:Wes DavisReport Date:28 Mar 2024

LIEBHERR

CONSTRUCTION EQUIPMENT





GRAPHS

