CONSTRUCTION EQUIPMENT

LIEBHERR A914 115625-1507 - Diesel Engine

PETRO CANADA DURON UHP 5W30

Sample No: LH0250433

Oil Type:

SAMPLE INFORMATION

Sample Number	LH0250433	LH0195703	
Sample Date	31 Mar 2024	27 Sep 2021	
Machine Hours	8962	2021	
Oil Hours	0	0	
Oil Changed	N/A	Changed	
Sample Status	NORMAL	NORMAL	

OIL CO	DNDITION			
/isc @ 100°C	cSt	10.4	0 11.9	
Dxidation (PA)	%	57	155	

CONT		ATION		
Water	%	NEG	NEG	
Soot %	%	0 ()	0 0	
Nitration (PA)	%	66	92	
Sulfation (PA)	%	50	94	
Glycol	%	NEG	NEG	
Fuel	%	<1.0	0.0	
Silicon	ppm	02	0 48	
Sodium	ppm	○ <1	0 6	
Potassium	ppm	2	02	

WEAR METALS

Iron	ppm	3	52	
Copper	ppm	○ <1	○ 71	
Lead	ppm	○ <1	03	
Tin	ppm	0	○ <1	
Aluminum	ppm	02	03	
Chromium	ppm	0	0 2	
Molybdenum	ppm	8	0 37	
Nickel	ppm	0 ()	○ <1	
Titanium	ppm	0	0	
Silver	ppm	0	0	
Manganese	ppm	0 🔘	2	
Vanadium	ppm	0	0	

	DITIVES	
lcium	ppm	1979
anosium	nom	133

Calcium	ppm	1979	0 1737	
Magnesium	ppm	133	○ 715	
Zinc	ppm	988	937	
Phosphorus	ppm	0 843	○ 764	
Barium	ppm	0	07	
Boron	ppm	02	50	





DECLAN KELLY EXCAVATIONS

41 DONNA STREET NEPEAN, ON CA K2G 2V5 Contact: Declan Kelly Deckelly86@gmail.com T: F:

Diagnosis

Confirm the source of the lubricant being utilized for top-up/fill. Resample at the next service interval to monitor.All component wear rates are normal. There is no indication of any contamination in the oil. Additive levels indicate the addition of a different brand, or type of oil. The condition of the oil is acceptable for the time in service.

Depot: Unique No: Signed: Report Date: DECNEP 5750628 Wes Davis 01 Apr 2024

CONSTRUCTION EQUIPMENT



GRAPHS

 \odot

