LIEBHERR

CONSTRUCTION EQUIPMENT

LIEBHERR LH50 80368 - Diesel Fuel


Sample No: LH0287892

ppm


0

Silicon

Oil Type: No.2 DIESEL FUEL (LOW-SULPHUR)







Diagnosis

F:

We advise that you check for faulty combustion, plugged air filters, or aftercoolers. We advise that you check the fuel injection system. Please contact your representative for information regarding the proper sampling kits for your service.{not applicable} We could not determine the source of darkness in the fuel. Sample was centrifuged to determine if material would separate, but no separation occurred. Not enough sample submitted to determine fuel condition and/or classification.

Depot:JDISUSUnique No:5760664Signed:Kevin MarsonReport Date:23 Apr 2024

Contact/Location: Mike Coates - JDISUS







Graphs

