LIEBHERR

CONSTRUCTION EQUIPMENT



[BLANCHARD] LIEBHERR LH22 139277 - Rear Left Wheel Hub

Sample No: LH0282722

Oil Type: GEAR OIL SAE 75W90

_				
J Sam	ple Infor	mation		
Sample Number		LH0282722	 	
Sample Date		08 Apr 2024	 	
Machine Hours		2161	 	
Oil Hours		0	 	
		N/A		
Oil Changed		NORMAL	 	
Sample Status		NORMAL	 	
Oil C	ondition			
Visc @ 40°C	cSt	105	 	
-4				
Cont	aminatio	. m		
Water	%	NEG	 	
Silicon	ppm	0	 	
Sodium	ppm	2	 	
Potassium	ppm	○ <1	 	
Wed	ır Metals	i		
Iron	ppm	10	 	
Copper	ppm	1	 	
Lead	ppm	0	 	
Tin	ppm	0	 	
Aluminum	ppm	() <1	 	
Chromium	ppm	0	 ***	
Molybdenum	ppm	0	 	
Nickel	ppm	0	 	
Titanium	ppm	0	 	
Silver	ppm	0	 	
Manganese	ppm	0 <1	 	
Vanadium	ppm	0	 	
Addi	itives			
Calcium	ppm	113	 	
Magnesium	ppm	2	 	
Zinc	ppm	48	 	
Phosphorus	ppm	1331	 	



LIEBHERR CANADA LTD.

1015 SUTTON DRIVE BURLINGTON, ON CA L7L 5Z8

Contact: Steve Lehto steve.lehto@liebherr.com

T: (905)319-9222 F: (905)319-6617

Diagnosis

Resample at the next service interval to monitor. The fluid was not specified, however, a fluid match indicates that this fluid is (GENERIC) GEAR OIL SAE 75W90. Please confirm.

All component wear rates are normal. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.

Depot: LIEMIS
Unique No: 5762065
Signed: Wes Davis
Report Date: 15 Apr 2024

Submitted By: Eric Leblond

<1</p>

267

ppm

ppm

Barium

Boron

LIEBHERR

CONSTRUCTION EQUIPMENT





Graphs

