

LIEBHERR

CONSTRUCTION EQUIPMENT



LIEBHERR L586 059873-1334 - Splitter Box

Sample No: LH

Oil Type: GEAR OIL SAE 80W90



Sample Information

Sample Number	LH	LH0224799	LH0250083	LH0242700
Sample Date	09 Apr 2024	30 Oct 2023	05 Jun 2023	05 Nov 2022
Machine Hours	8009	7081	0	4989
Oil Hours	0	0	0	0
Oil Changed	Changed	Changed	Changed	Changed
Sample Status	NORMAL	NORMAL	NORMAL	NORMAL

Bird's Hill Gravel and Stone Ltd.

1 Terracon Place

Winnipeg, MB

CA R2J 4B3

Contact: Joel Malkoske

Jmalkoske@glacialagg.ca

T: (204)663-0064

F:



Oil Condition

Visc @ 40°C	cSt	173	141	166	160



Contamination

Water	%	NEG	NEG	NEG	NEG
Silicon	ppm	<1	2	3	6
Sodium	ppm	1	5	8	4
Potassium	ppm	<1	3	3	1



Wear Metals

Iron	ppm	25	36	84	91
Copper	ppm	3	<1	1	1
Lead	ppm	0	1	<1	<1
Tin	ppm	0	0	0	0
Aluminum	ppm	<1	<1	1	2
Chromium	ppm	<1	<1	<1	<1
Molybdenum	ppm	0	0	<1	<1
Nickel	ppm	<1	<1	2	<1
Titanium	ppm	0	0	0	<1
Silver	ppm	0	<1	0	0
Manganese	ppm	<1	<1	7	1
Vanadium	ppm	0	0	0	0



Additives

Calcium	ppm	51	122	93	79
Magnesium	ppm	5	7	30	9
Zinc	ppm	329	394	96	102
Phosphorus	ppm	2256	2055	2141	2247
Barium	ppm	<1	1	6	0
Boron	ppm	1	6	4	11

Diagnosis

Resample at the next service interval to monitor. All component wear rates are normal. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.

Depot: BIRWIN

Unique No: 5762123

Signed: Kevin Marson

Report Date: 17 Apr 2024

Submitted By: Vincent Blanchette



Graphs

